



PN58HHG

report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | VOLKSWAGEN     |
| Model               | FOX            |
| Colour              | Red            |
| Year of manufacture | 2008           |
| Top speed           | 92 mph         |
| 0 - 60 mph          | 17.5 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 55 BHP              |
| Max. torque             | 108 Nm at 3.000 rpm |
| Engine capacity         | 1.198 cc            |
| Cylinders               | 3                   |
| Fuel type               | Petrol              |
| Consumption city        | 36.2 mpg            |
| Consumption extra urban | 55.4 mpg            |
| Consumption combined    | 46.3 mpg            |
| CO2 emission            | 139 g/km            |
| CO2 label               | E                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-29                  |
| Pictures      | 16                          |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-11-07 |
| MOT pass rate      | 76 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 4          |
| Total advice items | 19         |
| Total items failed | 11         |

|                  |  |
|------------------|--|
| MOT #17          | 2023-11-08 16:06   |
| MOT test number  | 377568919148   |
| Result           | ✓ Passed   |
| Next expiry date | 2024-11-07   |
| Advice           | Tyre slightly damaged/cracking or perishing all tyres slight cracking (5.2.3 (d) (ii)) |

|                 |   |
|-----------------|---|
| MOT #16         | 2023-10-19 12:48  |
| MOT test number | 416585600667  |
| Result          | ✗ Failed  |
| Fail            | Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))            |
| Fail            | Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) |
| Fail            | Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))                       |
| Fail            | Brake lever has insufficient reserve travel (1.1.2 (a))                       |

|                 |   |
|-----------------|---|
| MOT #15         | 2022-08-19 13:26  |
| MOT test number | 893589237189  |
| Result          | ✓ Passed  |
| Advice          | Rear Suspension arm corroded but not seriously weakened beam axle (5.3.3 (b) (i)) |
| Advice          | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))                |
| Advice          | Manufactures under trays and engine covers on vehicle                             |

**MOT #14**

2021-09-15 09:31

**MOT test number**

507900234750

**Result**

✓ Passed

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13**

2021-09-09 13:32

**MOT test number**

947258282702

**Result**

✗ Failed

**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12**

2020-11-13 09:24

**MOT test number**

583656181344

**Result**

✓ Passed

**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Covers fitted obstructing view**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #11** 2019-05-24 09:39**MOT test number** 768161880966**Result** ✓ Passed**MOT #10** 2018-05-29 13:52**MOT test number** 302275208630**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**Advice** Both rear tyres surface cracking**MOT #9** 2017-06-01 08:38**MOT test number** 244453211341**Result** ✓ Passed**MOT #8** 2016-07-21 13:36**MOT test number** 381313797903**Result** ✓ Passed**MOT #7** 2016-07-20 09:47**MOT test number** 971535831350**Result** ✗ Failed**Fail** Offside Headlamp aim too high (1.8)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #6** 2015-09-03 11:44**MOT test number** 285073051120**Result** ✓ Passed

**MOT #5** 2014-09-04 17:48**MOT test number** 566077644254**Result** ✓ Passed**MOT #4** 2014-09-04 12:23**MOT test number** 499247544202**Result** ✗ Failed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #3** 2013-08-10 09:04**MOT test number** 358542623240**Result** ✓ Passed**MOT #2** 2012-08-18 10:38**MOT test number** 407661032256**Result** ✓ Passed**MOT #1** 2011-08-27 09:42**MOT test number** 308619831452**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
7 November 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 January           |
| <b>Days left</b>        | 246                             |
| <b>MOT expiry date</b>  | 7 November 2024                 |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 48         |
| <b>Band</b>                                    | E          |
| <b>Single payment (12 months)</b>              | £ 180,00,- |
| <b>Single six month payment</b>                | £ 99,00,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 189,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>PN58HHG</b> |
| Plate since          | 2019-06-29     |
| Current registration | <b>PN58HHG</b> |
| Plate since          | 2019-06-29     |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 19                       |
| First mileage registration | 2008-09-01               |
| Last registration          | 2023-11-08               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2008-09-01 | 18 mi     |
| Registration #2  | 2011-08-27 | 10.080 mi |
| Registration #3  | 2012-08-18 | 12.599 mi |
| Registration #4  | 2013-08-10 | 14.905 mi |
| Registration #5  | 2014-09-04 | 19.519 mi |
| Registration #6  | 2014-09-04 | 19.519 mi |
| Registration #7  | 2015-09-03 | 31.348 mi |
| Registration #8  | 2016-07-20 | 32.195 mi |
| Registration #9  | 2016-07-21 | 32.195 mi |
| Registration #10 | 2017-06-01 | 46.103 mi |
| Registration #11 | 2019-05-20 | 55.377 mi |
| Registration #12 | 2019-05-20 | 55.377 mi |
| Registration #13 | 2019-05-20 | 55.377 mi |
| Registration #14 | 2019-05-20 | 55.377 mi |
| Registration #15 | 2019-05-20 | 55.377 mi |
| Registration #16 | 2019-05-20 | 55.377 mi |
| Registration #17 | 2019-05-20 | 55.377 mi |
| Registration #18 | 2019-05-20 | 55.377 mi |
| Registration #19 | 2019-05-20 | 55.377 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1660 mm |
| Height              | 1544 mm |
| Length              | 3828 mm |
| Wheel base          | 2465 mm |
| Kerb weight         | 1069 kg |
| Max. allowed weight | 1480 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 3                     |

|                 |            |
|-----------------|------------|
| Number of seats | 4          |
| Number of axles | 2          |
| Engine number   | BMD 378141 |