





report date: 2024-03-29

General information

Make	CITROEN
Model	C3 PICASSO PURETECH EDITION PICASSO
Colour	Grey
Year of manufacture	2017
Top speed	116 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-01-29

Pictures 5

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-10
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	12
Total items failed	0

MOT #7		2023-10-30 12:42
MOT test	number	980736242003
Result		✓ Passed
Next expi	ry date	2024-11-10
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6		2022-11-11 11:59
MOT test	number	884088158330
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))

MOT #5	2021-11-05 12:51
MOT test number	239754406493
Result	✓ Passed
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/11



MOT #4 2021-11-05 09:53

MOT test number 520995159276

Result

× Failed

DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #3 2020-10-19 08:17

MOT test number 230251699607

Result \(\sqrt{Passed} \)

MOT #2 2020-10-19 07:00

MOT test number 673293347376

Result × Failed

DANGEROUS Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure outer sidewall (5.2.3 (d) (ii))

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

MOT #1 2020-02-10 11:16

MOT test number 975402665671

CarCheck.co.uk page 4/11



Tax & MOT check

Tax expired: 1 March 2024





Expires: 10 November 2024

Tax status	Expired at 1 March 2024
Days left	60 days too late
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	*********	
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	***************************************	
See in this check if this CITROEN had different number plates.		More info >
器 UK	Plate changes	
THE REPORT OF THE PROPERTY OF	See in this check if this CITROEN had different number plates.	
THE REPORT OF THE PROPERTY OF	Number of plates	,
Plate since	Current registration	NK SIZ
Plate since	Plate since	
More info >	Current registration	UK UK
More info >	Plate since	
		More info >

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-04-29
Last registration	2023-10-30
Complete history	See info



Registration #1	2017-04-29	20 mi
Registration #2	2020-02-10	16.989 mi
Registration #3	2020-10-19	20.260 mi
Registration #4	2020-10-19	20.260 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	***
Adult	81%
Children	76%
Pedestrian	43%
Safety systems	40%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XVA30714560

CarCheck.co.uk page 11/11