



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO L1H1 2000 SPORTIVE CDTi
Colour	Silver
Year of manufacture	2017
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E






Internet history

Entry 2

Date	2021-10-09
Pictures	29
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-05
Pictures	10
Listing price	View report



source: [heycar.co.uk](#)



MOT history

MOT expiry date	2024-05-15
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #6	2023-05-16 12:48
MOT test number	812822472084
Result	✓ Passed
Next expiry date	2024-05-15
Advice	REAR SUSPENSION ARM BUSHES PERISHING SLIGHTLY
Advice	N/S FRONT STRUT TOP BEARING IS GETTING TIGHT

MOT #5	2023-05-11 10:07
MOT test number	150842427036
Result	✗ Failed
Advice	N/S FRONT STRUT TOP BEARING IS GETTING TIGHT
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge VERY LOW (5.2.3 (e))
Advice	OIL LIGHT FLASHING (SERVICE LIGHT MAYBE)
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail	Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))
Advice	REAR SUSPENSION ARM BUSHES PERISHING SLIGHTLY
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #4** 2022-04-28 11:54**MOT test number** 150819783424**Result** ✓ Passed**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #3** 2021-05-14 11:56**MOT test number** 389733669299**Result** ✓ Passed**Advice** Nearside Front Upper chip in windscreen**MOT #2** 2021-01-22 15:05**MOT test number** 649707266933**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))**MOT #1** 2020-01-13 08:31**MOT test number** 101690035665**Result** ✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	EN66VPA
Plate since	2019-03-29
Current registration	EN66VPA
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-01-25
Last registration	2023-05-16
Complete history	See info



Registration #1	2017-01-25	23 mi
Registration #2	2020-01-13	42.872 mi
Registration #3	2021-01-22	49.899 mi
Registration #4	2021-05-14	51.348 mi
Registration #5	2023-05-16	51.348 mi
Registration #6	2023-05-16	51.348 mi
Registration #7	2023-05-16	51.348 mi
Registration #8	2023-05-16	51.348 mi
Registration #9	2023-05-16	51.348 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1290 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	330A10006334704 LN9