





### General information

| Make                | JAGUAR         |
|---------------------|----------------|
| Model               | XJS 4.0        |
| Colour              | Green          |
| Year of manufacture | 1992           |
| Top speed           | 147 mph        |
| 0 - 60 mph          | 6.9 seconds    |
| Gearbox             | 5 speed Manual |

## Engine & fuel consumption

| Power           | 223 BHP             |
|-----------------|---------------------|
| Max. torque     | 376 Nm at 4.000 rpm |
| Engine capacity | 3.980 cc            |
| Cylinders       | 6                   |
| Fuel type       | Petrol              |
|                 |                     |





# Internet history


Entry 1

Date Pictures 2021-08-05

Listing price

View report

9



source: autotrader.co.uk



# MOT history

| MOT expiry date    | 2024-10-09 |
|--------------------|------------|
| MOT pass rate      | 56 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 8          |
| Total advice items | 15         |
| Total items failed | 27         |

| MOT #18  | 2023-10-10 13:08 |
|--|------------------|
| MOT test number  | 761799093395     |
| Result   | 🗸 Passed         |
| Next expiry date   | 2024-10-09       |
| Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |
| Advice Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |

| MOT #17   | 2023-09-28 11:25      |
|---|-----------------------|
| MOT test number   | 910546931637          |
| Result  | 🗙 Failed              |
| Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))    |                       |
| Fail Nearside Front Steering rack gaiter missing or no longer prevents the ingress of | dirt (2.1.3 (g) (ii)) |
| Fail Stop lamp(s) all not working (4.3.1 (a) (iii))                                   |                       |
| Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                  |                       |
| <b>Fail</b> Windscreen wiper not working (3.4 (a))                                    |                       |
| <b>Fail</b> Parking brake inoperative on one side both (1.4.1 (a))                    |                       |
| Advice Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))                   |                       |



| J199         | RPL        |
|--------------|------------|
| report date: | 2024-03-29 |

| MOT #16   | 2022-12-15 11:41 |
|---|------------------|
| MOT test number   | 842494107081     |
| Result  | 🗙 Failed         |
| <b>Fail</b> Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))                    |                  |
| <b>Fail</b> Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) |                  |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))              |                  |
| Fail Stop lamp(s) not working (4.3.1 (a) (ii))  |                  |
| <b>Fail</b> Offside Rear Exhaust silencer likely to become detached (8.1.1 (b) (ii))      |                  |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))              |                  |

| МОТ #15   | 2021-12-08 12:32 |
|---|------------------|
| MOT test number   | 469620182851     |
| Result  | ✓ Passed         |
| Advice Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c) | )                |

| MOT #14  | 2021-12-02 11:46 |
|--|------------------|
| MOT test number  | 314250514838     |
| Result   | × Failed         |
| Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))         |                  |
| Advice Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c)) |                  |
| Fail Stop lamp(s) all not working (4.3.1 (a) (iii))  |                  |
| Fail Windscreen wiper missing (3.4 (a))  |                  |





| MOT #13  |   | 2020-10-28 11:43 |
|----------|---|------------------|
| MOT test | number  | 570582809666     |
| Result   |   | 🗸 Passed         |
| Advice   | Offside Front Seat belt buckle slightly damaged (7.1.2 (d)) |                  |
| Advice   | Oil leak, but not excessive (8.4.1 (a) (i))                 |                  |
| Advice   | Oil leak, but not excessive (8.4.1 (a) (i))                 |                  |

| MOT #12  | 2019-10-10 10:38 |
|--|------------------|
| MOT test number  | 176537387810     |
| Result   | ✓ Passed         |
| Advice Offside Front Seat belt buckle slightly damaged (7.1.2 (d)) |                  |

| MOT #11  | 2019-10-04 10:49 |
|--|------------------|
| MOT test number  | 404841753277     |
| Result   | 🗙 Failed         |
| Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))  |                  |
| FailWindscreen washer not working (3.5 (a))                        |                  |
| FailParking brake efficiency below requirements (1.4.2 (a) (i))    |                  |
| Advice Offside Front Seat belt buckle slightly damaged (7.1.2 (d)) |                  |

| MOT #10                 |   | 2018-10-19 16:27 |
|-------------------------|---|------------------|
| MOT test number         |   | 913308226325     |
| Result                  |   | ✓ Passed         |
|                         |   |                  |
| МОТ #9                  |   | 2018-10-19 16:26 |
| MOT test number         |   | 111855389898     |
| Result                  |   | 🗙 Failed         |
| Pass with rectification | Nearside Side repeater not working (4.4.1 (a) (ii)) |                  |





| MOT #8  | 2017-12-22 14:41   |
|---|--------------------|
| MOT test number   | 204843552649       |
| Result  | ✓ Passed           |
|   |                    |
| MOT #7  | 2017-12-19 14:03   |
| MOT test number   | 741647051838       |
| Result  | 🗙 Failed           |
| <b>Fail</b> Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)      |                    |
| Fail   Nearside Rear Shock absorber has a serious fluid leak (2.7.3)                        |                    |
| <b>Fail</b> Offside Front Tyre has a cut in excess of the requirements deep enough to reach | n the ply or cords |
| (4.1.D.1a)  |                    |
| FailNearside Front wheel bearing has excessive play (2.5.A.3c)                              |                    |
| <b>Fail</b> Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)     |                    |
| Fail   Parking brake: efficiency below requirements (3.7.B.7)                               |                    |
| Fail   Offside front brake binding (3.7.B.1)  |                    |
| Fail   Nearside Front Tyre has ply or cords exposed (4.1.D.1b)                              |                    |

| MOT #6          | 2016-12-07 09:05 |
|-----------------|------------------|
| MOT test number | 405497934092     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #5          | 2015-12-01 12:31 |

| MOT test number | 832291596030 |
|-----------------|--------------|
| Result          | ✓ Passed     |





| MOT #4                  | 2015-12-01 12:31  |
|-------------------------|---|
| MOT test number         | 129007738368  |
| Result                  | × Failed  |
| Pass with rectification | Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b) |
| Pass with rectification | Offside Headlamp aim too far to the right (1.8)                 |


| MOT #3          | 2014-08-22 14:34 |
|-----------------|------------------|
| MOT test number | 899594034276     |
| Result          | ✓ Passed         |

| МОТ #2                           | 2009-09-16 08:18 |
|----------------------------------|------------------|
| MOT test number                  | 162539359270     |
| Result                           | ✓ Passed         |
| Notice Front tyres worn on edges |                  |

| MOT #1  | 2009-09-10 12:53 |
|---|------------------|
| MOT test number   | 400743659286     |
| Result  | 🗙 Failed         |
| Notice Front tyres worn on edges  |                  |
| <b>Fail</b> Front Subframe mounting prescribed area is excessively corroded (2.4.A.3) |                  |



Tax & MOT check







### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |         |
|----------|---------|
| Date     |         |
| Category | Lamp    |
| Туре     |         |
| Damage 2 | AMPL    |
|          | E Store |
| Date     | 1. E    |
| Category | amt     |
| Туре     |         |

#### Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx  |             |
|---|-------------|
| ***********   |             |
| ********  |             |
| *******   |             |
| ***********   |             |
| ********  |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this JAGUAR had different number plates. |             |
| Number of plates  | 7           |
| Current registration  |             |
| Plate since   |             |
| Current registration  |             |
| Plate since   |             |
|   |             |





#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 20         |
| First mileage registration | 1992-02-03 |
| Last registration          | 2023-10-10 |
| Complete history           | See info   |



| Registration #1  | 1992-02-03 | 27 mi      |
|------------------|------------|------------|
| Registration #2  | 2009-09-10 | 99.122 mi  |
| Registration #3  | 2009-09-16 | 99.122 mi  |
| Registration #4  | 2014-08-22 | 99.584 mi  |
| Registration #5  | 2015-12-01 | 101.196 mi |
| Registration #6  | 2015-12-01 | 101.196 mi |
| Registration #7  | 2016-12-07 | 101.766 mi |
| Registration #8  | 2017-12-19 | 102.325 mi |
| Registration #9  | 2017-12-22 | 102.325 mi |
| Registration #10 | 2018-10-19 | 103.273 mi |
| Registration #11 |            | 11.707 est |
| Registration #12 |            | 11.777 esi |
| Registration #13 |            | 11.777 esi |
| Registration #14 |            | 11.777 esi |
| Registration #15 |            | 11.707 esi |
| Registration #16 |            | 11.777 esi |
| Registration #17 |            | 11.707 esi |
| Registration #18 |            | 11.777 est |
| Registration #19 |            | 11.777 mi  |
| Registration #20 |            | 10.207 est |
|                  |            |            |

More info >



| Dimensions & weight                 |                               |
|-------------------------------------|-------------------------------|
| Width                               | 1793 mm                       |
| Height                              | 1254 mm                       |
| Length                              | 4764 mm                       |
| Additional information              |                               |
|                                     |                               |
| Fuel tank capacity                  | 75                            |
| Fuel tank capacity<br>Fuel delivery | 75 l<br>Multi-Point Injection |
|                                     |                               |