





General information

| Make | PEUGEOT |
|---------------------|-------------------|
| Model | 5008 HDI SW SPORT |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 115 mph |
| 0 - 60 mph | 12.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 110 BHP |
|-------------------------|---------------------|
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 41.5 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-07-12 |
| Pictures | 1 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2023-08-12 |
|--------------------|------------|
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 34 |
| Total items failed | 4 |

| MOT #13 | 2022-08-09 09:11 |
|--|------------------|
| MOT test number | 158805986312 |
| Result | ✓ Passed |
| Next expiry date | 2023-08-12 |
| Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice Rear BUMP STOPS WEARING | |

| MOT #12 | 202 | 1-08-13 14:52 |
|---|--|---------------|
| MOT test | number 1 | 10489609349 |
| Result | | 🗸 Passed |
| Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) | | (b)) |
| Advice | Clutch pedal anti-slip provision missing | |





| MOT #11 | 2021-08-12 15:33 | |
|---|-------------------------------|--|
| MOT test number | 597964277848 | |
| Result | 🗙 Failed | |
| Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingr | ress of dirt (5.3.4 (b) (ii)) | |
| Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) | | |
| Advice Offside Front Shock absorbers light misting of oil or has limited damping e | ffect (5.3.2 (b)) | |
| Advice Clutch pedal anti-slip provision missing | | |

| MOT #10 | 2020-11-23 15:47 |
|-----------------|------------------|
| MOT test number | 570899840893 |
| Result | ✓ Passed |

| MOT #9 | 2019-11-16 11:18 |
|--|------------------|
| MOT test number | 565681033975 |
| Result | ✓ Passed |
| Advice Both wipers slightly smeary | |
| Advice Front tyres are wearing their edges | |

| MOT #8 | 2019-11-14 16:54 |
|---|------------------|
| MOT test number | 888938445175 |
| Result | 🗙 Failed |
| Advice Both wipers slightly smeary | |
| Advice Front tyres are wearing their edges | |
| Fail Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i)) | |





| MOT #7 | 2019-01-16 11:29 |
|--|--------------------------|
| MOT test number | 945308642902 |
| Result | ✓ Passed |
| Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in ex Rear (5.3.4 (a) (i)) | cessive movement |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or l (i)) | light sources (4.7.1 (b) |
| Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in a Rear (5.3.4 (a) (i)) | excessive movement |
| MOT #6 | 2018-01-09 12:36 |
| MOT test number | 823544674997 |
| Result | ✓ Passed |
| Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in rear bush (2.4.G.2) | excessive movement |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |) |
| Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting i | in excessive movement |

rear bush (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

| MOT #5 | 2017-01-14 11:57 |
|---|-----------------------------|
| MOT test number | 787533498525 |
| Result | ✓ Passed |
| Advice Nearside Front Suspension arm rubber bush deteriorated but not resul rear bush (2.4.G.2) | lting in excessive movement |
| Advice Engine covers and under car covers not allowing full inspection | |
| Advice Offside Front Suspension arm rubber bush deteriorated but not resultine rear bush (2.4.G.2) | ng in excessive movement |





| MOT #4 | | 2017-01-14 11:57 |
|---|--|------------------|
| MOT test number | | 527193329461 |
| Result | | 🗙 Failed |
| Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2) | | |
| Pass with rectification | Nearside Front position lamp(s) not work | ing (1.1.A.3b) |
| Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2) | | |
| Advice Engine covers a | nd under car covers not allowing full inspec | ction |

| MOT #3 | 2016-01-09 11:02 |
|---|------------------|
| MOT test number | 970541428626 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #2 | | 2015-01-08 12:25 |
|----------|--|------------------|
| MOT test | number | 407868705085 |
| Result | | ✓ Passed |
| Advice | Offside Rear Brake pad(s) wearing thin (3.5.1g) | |
| Notice | Front tyres wearing on inner edge | |
| Advice | Nearside Rear Brake pad(s) wearing thin (3.5.1g) | |





| MOT #1 | | 2014-01-04 11:33 |
|---|--|------------------|
| MOT test | number | 566434704090 |
| Result | | ✓ Passed |
| Advice | Offside Front brake disc worn, pitted or scored, but not seriously weakene | ed (3.5.1i) |
| Advice | Offside Front Brake pad(s) wearing thin (3.5.1g) | |
| Advice | vice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |
| Advice | Nearside Front Brake pad(s) wearing thin (3.5.1g) | |
| Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7) | | |



KM60XAX report date: 2024-03-28

Tax & MOT check

| X Untaxed Tax expired: 12 June 2023 | X MOT Expired: 12 August 2023 |
|--|--|
| Tax status | Expired at 12 June 2023 |
| Days left | 323 days too late |
| MOT expiry date | 12 August 2023 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---|
| Date | |
| Category | 4. DEM PE |
| Туре | |
| Damage 2 | Annet |
| Date | No. Contraction of the second |
| Category | AMP |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******* | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2010-12-21 |
| Last registration | 2022-08-09 |
| Complete history | See info |



| Registration #1 | 2010-12-21 | 8 mi |
|------------------|------------|------------|
| Registration #2 | 2014-01-04 | 48.410 mi |
| Registration #3 | 2015-01-08 | 60.959 mi |
| Registration #4 | 2016-01-09 | 74.458 mi |
| Registration #5 | 2017-01-14 | 85.381 mi |
| Registration #6 | 2017-01-14 | 85.381 mi |
| Registration #7 | 2018-01-09 | 94.506 mi |
| Registration #8 | 2019-01-16 | 107.677 mi |
| Registration #9 | | 11.777 est |
| Registration #10 | | 11.117 esi |
| Registration #11 | | 11.777 esi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 esi |





Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 0566 | |
| 0567 | |
| 0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|------------------------|
| Adult | 82% |
| Children | 81% |
| Pedestrian | 53% |
| Safety systems | 83% |
| Overall rating | 76% |
| Video | <u>see crash video</u> |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1815 mm |
| Height | 1560 mm |
| Length | 4500 mm |
| Wheel base | 2708 mm |
| Kerb weight | 1570 kg |
| Max. allowed weight | 2150 kg |
| Additional information | |
| Fuel tank capacity | 60 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 14/14 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | JBBN0297342 |