



LR59FMV

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 LWB HR P/V 115
Colour	White
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	310 Nm at 1.750 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-06-18
Pictures	0
Listing price	View report

source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-01
Pictures	19
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-08-09
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	27
Total items failed	21

MOT #18	2023-08-10 14:04
MOT test number	749692143421
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Nearside Rear light lens slightly damaged
Advice	Prop shaft bearing has slight play (6.1.7 (b) (i))
Minor	Front Position lamp with a multiple light source up to 1/2 not functioning high level (4.2.1 (a) (i))
Advice	Light misting of oil on both steering rack gaitors

MOT #17	2023-08-10 14:04
MOT test number	423874993348
Result	✗ Failed
Pass with rectification	Offside Rear Position lamp not working (4.2.1 (a) (ii))
Advice	Light misting of oil on both steering rack gaitors
Advice	Prop shaft bearing has slight play (6.1.7 (b) (i))
Minor	Front Position lamp with a multiple light source up to 1/2 not functioning high level (4.2.1 (a) (i))
Advice	Nearside Rear light lens slightly damaged



MOT #16	2022-12-22 09:35
MOT test number	298748097255
Result	✓ Passed

MOT #15	2022-12-08 09:41
MOT test number	261273265772
Result	✗ Failed
<div><div>Fail</div> Anti-lock braking system warning lamp does not illuminate (1.6 (a))</div> <div><div>Fail</div> Rear Stop lamp(s) all not working (4.3.1 (a) (iii))</div>	

MOT #14	2021-12-10 11:28
MOT test number	974165670306
Result	✓ Passed

**MOT #13** 2021-12-08 15:45**MOT test number** 210074969446**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear tyre deflated**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))**Advice** Front both repeaters faded**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))**Advice** Rear lamp holder damaged**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**MOT #12** 2020-10-17 11:22**MOT test number** 232730432093**Result** ✓ Passed**MOT #11** 2020-10-17 11:22**MOT test number** 951870961662**Result** ✗ Failed**Pass with rectification** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

**MOT #10**

2019-03-13 16:21

MOT test number

519509810075

Result

✓ Passed

Advice Offside Front tyre uneven wear**Advice** Nearside Front tyre uneven wear**MOT #9**

2019-03-09 09:35

MOT test number

916963528106

Result

✗ Failed

Fail Nearside Rear Position lamp not working (4.2.1 (a))**Advice** Nearside Front tyre uneven wear**Fail** Nearside Rear Brake disc contaminated (1.1.14 (b))**Fail** Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Front tyre uneven wear**Fail** Offside Rear Brake disc contaminated (1.1.14 (b))**MOT #8**

2018-04-11 09:26

MOT test number

810833619843

Result

✓ Passed

Advice EML lamp on**MOT #7**

2017-02-11 13:04

MOT test number

482515211054

Result

✓ Passed

Advice Offside Side repeater slightly discoloured (1.4.A.2f)**Advice** Engine management light indicates a fault**Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)

**MOT #6** 2017-02-09 15:08**MOT test number** 658273467819**Result** ✗ Failed**Fail** Nearside rear brake excessively fluctuating (3.7.B.3)**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Headlamp aim too high (1.8)**Advice** Engine managment light indicates a fault**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)**MOT #5** 2015-11-04 11:00**MOT test number** 951971889926**Result** ✓ Passed**MOT #4** 2015-01-13 11:26**MOT test number** 797493915044**Result** ✓ Passed**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)



MOT #3	2015-01-13 11:26
MOT test number	385343415044
Result	✗ Failed
Advice	Offside Side repeater slightly discoloured (1.4.A.2f)
Pass with rectification	Electrical wiring insecure (1.9.2a)

MOT #2	2014-01-15 09:17
MOT test number	529805814091
Result	✓ Passed

MOT #1	2013-01-04 10:04
MOT test number	585424003050
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 August 2024

Tax status	Valid until 1 April
-------------------	---------------------

Days left	336
------------------	-----

MOT expiry date	9 August 2024
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	LR59FMV
Plate since	2019-03-29
Current registration	LR59FMV
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-01-25
Last registration	2023-08-10
Complete history	See info



Registration #1	2010-01-25	23 mi
Registration #2	2013-01-04	39.338 mi
Registration #3	2014-01-15	54.146 mi
Registration #4	2015-01-13	68.782 mi
Registration #5	2015-11-04	76.955 mi
Registration #6	2017-02-09	86.206 mi
Registration #7	2017-02-11	86.206 mi
Registration #8	2018-04-11	93.995 mi
Registration #9	2019-03-09	99.324 mi
Registration #10	2019-03-13	99.327 mi
Registration #11	2019-03-20	99.337 mi
Registration #12	2019-03-20	99.337 mi
Registration #13	2019-03-20	99.337 mi
Registration #14	2019-03-20	99.337 mi
Registration #15	2019-03-20	99.337 mi
Registration #16	2019-03-20	99.337 mi
Registration #17	2019-03-20	99.337 mi
Registration #18	2019-03-20	99.337 mi
Registration #19	2019-03-20	99.337 mi
Registration #20	2019-03-20	99.337 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	2601 mm
Length	5680 mm
Kerb weight	1790 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	AT18351