



report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO HDI 600 LX SWB H/C CDV
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	175 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT #15	2021-10-13 15:05
MOT test number	527459884150
Result	✓ Passed
Next expiry date	2022-10-12

MOT #14	2020-08-11 10:09
MOT test number	642809724363
Result	✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13	2020-07-29 15:09
MOT test number	249699209589

Result	✗ Failed
---------------	----------

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Horn not working (7.7 (a) (ii))

Fail Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

**MOT #12**

2017-01-11 09:59

MOT test number

327748552067

Result

✓ Passed

Advice Power steering component(s) has slight seepage from a component (2.3.3b)**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Trailing arm has slight play in a pin bearing (2.4.G.2)**Advice** Brake pipe slightly corroded all (3.6.B.2c)**Advice** Engine oil leak**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Trailing arm has slight play in a pin bearing (2.4.G.2)**MOT #11**

2017-01-10 10:34

MOT test number

113675093555

Result

✗ Failed

Fail Parking brake: efficiency below requirements (3.7.B.7)**Advice** Engine oil leak**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Trailing arm has slight play in a pin bearing (2.4.G.2)**Fail** Horn not working (1.6.2a)**Advice** Brake pipe slightly corroded all (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Trailing arm has slight play in a pin bearing (2.4.G.2)



MOT #10	2016-01-19 15:39
MOT test number	493298480294
Result	✓ Passed
Advice	Front Windscreen Chipped At Passengers Side

MOT #9	2016-01-13 14:35
MOT test number	435798782995
Result	✗ Failed
Fail	Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Fail	Nearside Steering system has excessive free play detected at the steering wheel (steering rack fitted) (2.2.A.1b)
Fail	Offside Stop lamp not working (1.2.1b)

MOT #8	2015-01-26 14:32
MOT test number	509006925017
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	N/s/r wheel tight to turn
Advice	Power steering component(s) has slight seepage from a component (2.3.3b)
Notice	Play in steering rack inner joint(s)

**MOT #7**

2015-01-26 11:28

MOT test number

176006225445

Result**✗ Failed**

- Notice** Play in steering rack inner joint(s)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** N/s/r wheel tight to turn
- Advice** Power steering component(s) has slight seepage from a component (2.3.3b)
- Fail** Horn not working (1.6.2a)

MOT #6

2014-01-15 15:51

MOT test number

475875914035

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Slight bind at nearside front brake
- Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Play in steering rack inner joint(s)

MOT #5

2014-01-15 10:03

MOT test number

546965714089

Result**✗ Failed**

- Fail** Rear brake application uneven (3.7.B.2)
- Notice** Slight bind at nearside front brake
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside rear brake binding (3.7.B.1)
- Notice** Play in steering rack inner joint(s)
- Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #4**

2013-01-15 15:55

MOT test number

856595413082

Result

✓ Passed

Advice Power steering component(s) has slight seepage from a component (2.3.3b)**Notice** O/s/f wheel twisted slightly**Notice** Oil leak**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Eml light on**MOT #3**

2013-01-15 10:36

MOT test number

338635913032

Result

✗ Failed

Notice Oil leak**Fail** Offside Stop lamp not working (1.2.1b)**Notice** O/s/f wheel twisted slightly**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Eml light on**Notice** O/s/f top strut bearing slightly rough**Fail** Offside Front coil spring fractured (2.4.C.1a)**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)

**MOT #2** 2012-01-17 14:48**MOT test number** 956977612031**Result** ✓ Passed

Advice Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice Oil leak

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice Exhaust deteriorated

Advice Front brake juddering slightly (3.7.A.2b)

MOT #1 2011-01-07 11:45**MOT test number** 236417201044**Result** ✓ Passed

Notice Rear silencer bracket corroded

Advice Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Both front brake discs slightly worn

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Oil leak



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-12-20
Last registration	2021-10-13
Complete history	See info



Registration #1	2007-12-20	20 mi
Registration #2	2011-01-07	36.236 mi
Registration #3	2012-01-17	45.435 mi
Registration #4	2013-01-15	51.364 mi
Registration #5	2013-01-15	51.364 mi
Registration #6	2014-01-15	56.485 mi
Registration #7	2014-01-15	56.485 mi
Registration #8	2015-01-26	61.419 mi
Registration #9	2015-01-26	61.419 mi
Registration #10	2015-01-26	61.419 mi
Registration #11	2015-01-26	61.419 mi
Registration #12	2015-01-26	61.419 mi
Registration #13	2015-01-26	61.419 mi
Registration #14	2015-01-26	61.419 mi
Registration #15	2015-01-26	61.419 mi
Registration #16	2015-01-26	61.419 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width 1960 mm

Length 4137 mm

Additional information

Fuel delivery Direct Injection

Number of doors 5

Number of seats 2

Engine number JB790089331