



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Silver
Year of manufacture	2009
Top speed	128 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-13
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-13
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	31
Total items failed	12

MOT #18	2023-10-14 08:31
MOT test number	103870305874
Result	✓ Passed
Next expiry date	2024-10-13
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #17	2023-10-07 09:28
MOT test number	487521753468
Result	✗ Failed
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Fail	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #16	2022-10-04 13:03
MOT test number	487341100392
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #15**

2022-10-03 14:44

**MOT test number**

517313453345

**Result****✗ Failed**

- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2021-09-30 14:10

**MOT test number**

243416972404

**Result****✓ Passed**

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear brake pad wear appears to be low
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2021-09-24 12:41

**MOT test number**

934189384782

**Result****✗ Failed****Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear brake pad wear appears to be low**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12**

2020-12-18 16:20

**MOT test number**

871708314078

**Result****✓ Passed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face. (1.1.14 (a) (ii))**MOT #11**

2019-11-29 14:20

**MOT test number**

945491871176

**Result****✓ Passed**

**MOT #10** 2019-11-29 08:40**MOT test number** 225712299359**Result** ✗ Failed**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**MOT #9** 2018-12-22 10:21**MOT test number** 250874190817**Result** ✓ Passed**MOT #8** 2017-11-07 14:43**MOT test number** 414106109794**Result** ✓ Passed**MOT #7** 2017-11-07 08:36**MOT test number** 806387784115**Result** ✗ Failed**Advice** Nearside Rear tyre damaged outer sidewall and deep split in tread**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2016-09-14 07:33**MOT test number** 102788474890**Result** ✓ Passed**MOT #5** 2015-09-29 08:02**MOT test number** 288687445312**Result** ✓ Passed

**MOT #4** 2014-12-15 09:54**MOT test number** 298149344334**Result** ✓ Passed

- Notice** Nearside rear lamp unit damaged
- Notice** Rear tyres worn inner edge and slightly deteriorated
- Notice** Slight damage outer sidewall nearside front tyre and offside rear tyre

**MOT #3** 2014-12-15 09:54**MOT test number** 856279244315**Result** ✗ Failed

- Notice** Slight damage outer sidewall nearside front tyre and offside rear tyre
- Notice** Nearside rear lamp unit damaged
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)
- Notice** Rear tyres worn inner edge and slightly deteriorated

**MOT #2** 2013-12-19 16:41**MOT test number** 875103653332**Result** ✓ Passed

- Notice** Nearside rear light lense broken

**MOT #1** 2012-12-27 10:33**MOT test number** 105102762356**Result** ✓ Passed

- Advice** Offside Rear Seat belt stitching slightly frayed (5.2.2b)
- Notice** Offside wiper blade split



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
13 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	13 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-12-17
Last registration	2023-10-14
Complete history	<a href="#">See info</a>



Registration #1	2009-12-17	29 mi
Registration #2	2012-12-27	29.136 mi
Registration #3	2013-12-19	35.689 mi
Registration #4	2014-12-15	43.526 mi
Registration #5	2015-09-29	53.765 mi
Registration #6	2016-09-14	64.889 mi
Registration #7	2017-11-07	78.448 mi
Registration #8	2017-11-07	78.453 mi
Registration #9	2018-12-22	89.830 mi
Registration #10	2019-11-29	99.485 mi
Registration #11	2019-11-29	99.485 mi
Registration #12	2019-11-29	99.485 mi
Registration #13	2019-11-29	99.485 mi
Registration #14	2019-11-29	99.485 mi
Registration #15	2019-11-29	99.485 mi
Registration #16	2019-11-29	99.485 mi
Registration #17	2019-11-29	99.485 mi
Registration #18	2019-11-29	99.485 mi
Registration #19	2019-11-29	99.485 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1510 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBA 174034