





report date: 2024-03-28

General information

Make	PEUGEOT
Model	RCZ THP SPORT
Colour	Grey
Year of manufacture	2013
Top speed	133 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



BV63KUP report date: 2024-03-28

Internet history

_	_	_		_	-
드	n	C	ľν	7	1

Elitiy 1	
Date	2021-12-15
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-29
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	17
Total items failed	0

MOT #13	2024-01-30 15:07
MOT test number	135837943982
Result	✓ Passed
Next expiry date	2025-01-29

MOT #12	2024-01-25 09:45
MOT test number	624483364813
Result	X Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	ı

MOT #11		2023-01-26 17:01
MOT test number		633690044689
Result		✓ Passed
Minor Offside Front Driv	ve shaft joint constant velocity boot	severely deteriorated (6.1.7 (g) (i))

MOT #10	2022-01-04 13:36
MOT test number	319509758142
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2021-12-21 07:52

MOT test number 746575005531

Result X Failed

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

DANGEROUS Offside Front Suspension arm modified so the suspension is likely to foul other components (5.3.3 (c) (ii))

MOT #8 2021-09-14 16:00

MOT test number 599784872001

MOT #7 2021-09-14 10:07

MOT test number 154221472206

Result X Failed

MAJOR Offside Headlamp aim too high (4.1.2 (a))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #6 2020-09-11 15:17

MOT test number 662914812191

Result ✓ Passed

MOT #5 2019-09-11 15:58

MOT test number 142981606056

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Play in steering rack inner joint(s)

CarCheck.co.uk page 4/12



MOT #4

BV63KUP

report date: 2024-03-28

2019-09-11 14:06

MOT test number 456033023282

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Play in steering rack inner joint(s)

DANGEROUS Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #3 2018-09-04 13:03

MOT test number 713167655663

Result ✓ Passed

MOT #2 2017-09-12 17:52

MOT test number 403148522458

Result \(\sqrt{Passed} \)

Advice Tyre walls cutting but not deep enough to reach the ply or cords. nearside/offside

Advice Front Tyre worn close to the legal limit inner edges nearside/offside (4.1.E.1)

MOT #1 2016-09-02 11:59

MOT test number 240738673701

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	29 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



BV63KUP report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

,		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-01
Last registration	2024-01-30
Complete history	See info



Registration #1	2013-09-01	24 mi
Registration #2	2016-09-02	30.122 mi
Registration #3	2017-09-12	38.351 mi
Registration #4	2018-09-04	44.785 mi
Registration #5	2019-09-11	49.977 mi
Registration #6	2019-09-11	49.978 mi
Registration #7	2020-09-11	51.965 mi
Registration #8	2021-09-14	53.488 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es
D		
Registration #13		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12




BV63KUP report date: 2024-03-28

Car features

50225	Air conditionin
S0295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2107 mm
Height	1362 mm
Length	4290 mm
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Paralle a manufacture	FIDC17424CC

Engine number FJBS1742466 Carcheck.co.uk