



PEUGEOT

CA060HD


report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S COUPE CABRIOLET
Colour	Blue
Year of manufacture	2006
Top speed	129 mph
0 - 60 mph	10.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 4.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	192 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-11-16
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-15
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	89
Total items failed	10

MOT #21	2023-05-16 11:30
MOT test number	794641803561
Result	✓ Passed
Next expiry date	2024-05-15
Advice	Nearside Play in steering rack inner joint(s)
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Offside Play in steering rack inner joint(s)
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))

**MOT #20**

2023-05-09 15:32

MOT test number

663415955239

Result

✗ Failed

- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #19

2022-05-10 13:45

MOT test number

683098367101

Result

✓ Passed

- Advice** Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))



MOT #18

2022-05-05 11:20

MOT test number

370922572908

Result

✗ Failed

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #17

2021-02-02 13:54

MOT test number

467664253760

Result		✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))	
Advice	Play in steering rack inner joint(s)	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))	
Advice	Offside Play in steering rack inner joint(s)	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	

**MOT #16**

2021-02-01 12:23

MOT test number

825393344669

Result**✗ Failed**

- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #15

2020-02-05 08:57

MOT test number

472995368382

Result**✓ Passed**

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively when rotated by hand (1.2.1 (f))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2019-02-07 12:18

MOT test number

239527241124

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner and outer faces (1.1.14 (a) (ii))

Advice Offside Play in steering rack inner joint(s)

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened inner and outer faces (1.1.14 (a) (ii))

Advice Nearside Play in steering rack inner joint(s)

MOT #13

2019-02-07 08:59

MOT test number

714174172837

Result

✗ Failed

Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt drop link (5.3.4 (b) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner and outer faces (1.1.14 (a) (ii))

Advice Offside Play in steering rack inner joint(s)

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened inner and outer faces (1.1.14 (a) (ii))

Advice Nearside Play in steering rack inner joint(s)

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

MOT #12

2018-02-15 10:19

MOT test number

493138420107

Result

✓ Passed

**MOT #11** 2017-02-11 13:36**MOT test number** 187980190155**Result** ✓ Passed**MOT #10** 2016-02-16 16:20**MOT test number** 458593261870**Result** ✓ Passed**Advice** Rear brake discs corroded**Advice** Oil leak**MOT #9** 2015-02-10 12:51**MOT test number** 178181845409**Result** ✓ Passed**MOT #8** 2014-08-12 11:42**MOT test number** 599864924248**Result** ✓ Passed**Advice** Offside Drag link end ball joint has slight play (2.2.B.1f)**Notice** Coolant low**Advice** Nearside Drag link end ball joint has slight play (2.2.B.1f)

**MOT #7**

2014-08-12 10:42

MOT test number

297094824254

Result**✗ Failed****Notice**

Coolant low

Fail

Offside Registration plate lamp not working (1.1.C.1d)

Advice

Nearside Drag link end ball joint has slight play (2.2.B.1f)

Fail

Offside Rear position lamp(s) not working (1.1.A.3b)

Fail

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice

Offside Drag link end ball joint has slight play (2.2.B.1f)

MOT #6

2013-07-31 12:42

MOT test number

336072813263

Result**✓ Passed****Notice**

Slight play in both steering rack arms

Notice

Engine warning light on

MOT #5

2012-08-01 13:53

MOT test number

117684412291

Result**✓ Passed****Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice

Play in steering rack inner joint(s)

MOT #4

2011-08-03 11:51

MOT test number

385825011409

Result**✓ Passed**



MOT #3 2010-07-09 15:15

MOT test number 732960290138

Result ✓ Passed

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Notice Rear discs worn & lip

MOT #2 2009-06-29 16:34

MOT test number 852130589120

Result ✓ Passed

MOT #1 2009-06-29 11:28

MOT test number 283200789162

Result ✗ Failed

Notice Front brake discs worn and lip

Advice Steering system has slight free play detected at steering wheel (2.2.A.1b)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 May 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	15 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-07-17
Last registration	2023-05-16
Complete history	See info



Registration #1	2006-07-17	8 mi
Registration #2	2009-06-29	36.954 mi
Registration #3	2009-06-29	36.976 mi
Registration #4	2010-07-09	51.278 mi
Registration #5	2011-08-03	62.324 mi
Registration #6	2012-08-01	66.833 mi
Registration #7	2013-07-31	73.108 mi
Registration #8	2014-08-12	77.100 mi
Registration #9	2014-08-12	77.100 mi
Registration #10	2015-02-10	78.904 mi
Registration #11	2016-02-16	79.451 mi
Registration #12	2017-02-11	85.812 mi
Registration #13	2018-05-20	91.277 mi
Registration #14	2019-05-20	91.277 mi
Registration #15	2020-05-20	91.277 mi
Registration #16	2021-05-20	91.277 mi
Registration #17	2022-05-20	91.277 mi
Registration #18	2023-05-16	91.277 mi
Registration #19	2023-05-16	91.277 mi
Registration #20	2023-05-16	91.277 mi
Registration #21	2023-05-16	91.277 mi
Registration #22	2023-05-16	91.277 mi
Registration #23	2023-05-16	91.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1543 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	LH4P1445371