



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Grey
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-04-19
Pictures	8
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-12
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	18
Total items failed	1

MOT #11	2024-03-13 13:32
MOT test number	491431852137
Result	✓ Passed
Next expiry date	2025-03-12

MOT #10	2023-04-25 10:43
MOT test number	550733915242
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Brake pad(s) wearing thin Close to legal limit (1.1.13 (a) (ii))
Advice	Nearside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9	2022-02-14 11:07
MOT test number	302978021239
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2021-02-06 16:25

**MOT test number**

417834852745

**Result**

✓ Passed

**Advice** Rear Brake pad(s) wearing thin look low (1.1.13 (a) (ii))**Advice** Items removed from driver's view prior to test**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7**

2021-02-02 13:17

**MOT test number**

123755237931

**Result**

✗ Failed

**Advice** Rear Brake pad(s) wearing thin look low (1.1.13 (a) (ii))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Items removed from driver's view prior to test**MOT #6**

2020-02-03 11:04

**MOT test number**

322530932771

**Result**

✓ Passed

**MOT #5**

2018-11-29 14:20

**MOT test number**

139137542315

**Result**

✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))



MOT #4	2017-12-04 10:25
MOT test number	804779067396
Result	✓ Passed
MOT #3	2017-12-04 10:25
MOT test number	627850495615
Result	✗ Failed
<div>Pass with rectification</div> Nearside Headlamp aim too high (1.8)	
MOT #2	2016-12-13 16:12
MOT test number	554644046266
Result	✓ Passed
MOT #1	2015-09-04 16:43
MOT test number	675247153738
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
12 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	12 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-09-01
Last registration	2024-03-13
Complete history	<a href="#">See info</a>



Registration #1	2012-09-01	29 mi
Registration #2	2015-09-04	48.193 mi
Registration #3	2016-12-13	63.439 mi
Registration #4	2017-12-04	70.492 mi
Registration #5	2017-12-04	70.492 mi
Registration #6	2018-11-29	75.683 mi
Registration #7	2020-02-03	82.287 mi
Registration #8	2020-03-29	82.287 mi
Registration #9	2020-03-29	82.287 mi
Registration #10	2020-03-29	82.287 mi
Registration #11	2020-03-29	82.287 mi
Registration #12	2020-03-29	82.287 mi
Registration #13	2020-03-29	82.287 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Engine number	D4CBC995094
---------------	-------------