





report date: 2024-03-28

General information

| Make | HONDA |
|---------------------|-----------------------|
| Model | CR-Z I-VTEC IMA SPORT |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 124 mph |
| 0 - 60 mph | 10.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 113 BHP |
|-------------------------|---------------------|
| Max. torque | 145 Nm at 4.800 rpm |
| Engine capacity | 1.497 сс |
| Cylinders | 4 |
| Fuel type | Hybrid / Electric |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 117 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/12



Internet history

| Е, | 2+ | PA. | , 7 |) |
|----|----|-----|-----|---|
| | | | | |

| Date | 2022-11-14 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: carcraft.co.uk

Entry 1

| Date | 2022-07-20 |
|---------------|-------------|
| Pictures | 1 |
| Listing price | View report |



source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2025-02-08 |
|--------------------|------------|
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 7 |
| Total items failed | 4 |

| MOT #13 | | 2024-02-01 10:58 |
|--|--|------------------|
| MOT test | number | 314630432507 |
| Result | | ✓ Passed |
| Next expiry date 2025-02-0 | | 2025-02-08 |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #12 | 2023-02-09 09:33 |
|--|------------------|
| MOT test number | 873072880353 |
| Result | ✓ Passed |
| | |
| MOT #11 | 2021-10-01 15:53 |
| MOT test number | 264960575798 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #10 | 2020-09-22 16:07 |
|---|------------------|
| MOT test number | 300976555495 |
| Result | ✓ Passed |
| Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) | |

CarCheck.co.uk page 3/12



MOT #9 2020-09-22 08:36

MOT test number 749286427368

Result × Failed

Fail Nearside Rear Headlamp levelling device inoperative (4.1.5 (a))

Fail Headlamp aim too high (4.1.2 (a))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #8 2019-11-11 09:41

MOT test number 470965464711

Advice Offside Front Tyre slightly damaged (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2018-12-03 09:37

MOT test number 794992989510

Result \(\sqrt{Passed} \)

MOT #6 2017-12-06 13:22

MOT test number 265185145153

Result

Passed

MOT #5 2017-12-06 13:22

MOT test number 311649619954

Result × Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #4 2016-12-12 16:19

MOT test number 544598069552

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 4/12



MOT test number

Result

MOT test number

Result

MOT #2

2015-08-24 13:59

MOT test number

883178802645

Result

Pass with rectification

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

| MOT #1 | 2014-08-25 16:56 |
|-----------------|------------------|
| MOT test number | 349067934427 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 279 |
| MOT expiry date | 8 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 59 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 25,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 26,25,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is | | A |
|--|-----------|---|
| *************************************** | | |
| | | |
| *************************************** | | |
| ******** | | |
| | | |
| ************* | | |
| | More info | > |
| Plate changes | | |
| See in this check if this HONDA had different number plates. | | |
| Number of plates | | |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 9/12



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >


CarCheck.co.uk page 10/12



Mileage check

Registration #16

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2011-09-01 |
| Last registration | 2024-02-01 |
| Complete history | See info |



| Registration #1 | 2011-09-01 | 7 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-08-25 | 17.303 mi |
| Registration #3 | 2015-08-24 | 23.188 mi |
| Registration #4 | 2015-08-24 | 23.188 mi |
| Registration #5 | 2016-12-12 | 28.001 mi |
| Registration #6 | 2017-12-06 | 34.983 mi |
| Registration #7 | 2017-12-06 | 34.983 mi |
| Registration #8 | 2018-12-03 | 48.514 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 91.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 91.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| | | |

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 11/12



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 80% |
| Pedestrian | 71% |
| Safety systems | 86% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| Width | 2014 mm |
|-------------|---------|
| Height | 1395 mm |
| Length | 4080 mm |
| Wheel base | 2425 mm |
| Kerb weight | 1198 kg |

Additional information

| Fuel tank capacity | 40 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | LEA1 1004814 |

CarCheck.co.uk page 12/12