



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Silver
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-14
Pictures	60
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-08
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	31
Total items failed	9

MOT #17	2023-07-06 09:12
---------	------------------

MOT test number	284241502738
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-08
------------------	------------

Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Central Rear Sub-frame corroded but not seriously weakened spring carriers corroded (5.3.3 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear underbody corrosion
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2022-07-01 09:11

MOT test number

493312277301

Result

✓ Passed

- Advice** Covers fitted obscuring some components
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Exhaust corroding
- Advice** Front both tyres wearing on inner tread
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear both tyres stepping on inner tread
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view chipped (3.2 (a) (i))
- Advice** Corrosion to underside of vehicle

MOT #15

2021-07-09 09:00

MOT test number

416988353500

Result

✓ Passed

MOT #14

2021-06-16 11:05

MOT test number

760913951216

Result

✓ Passed

MOT #13

2020-11-02 08:07

MOT test number

658553885997

Result

✓ Passed

**MOT #12** 2019-05-03 08:50**MOT test number** 712272275173**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #11** 2018-05-02 15:19**MOT test number** 989653434894**Result** ✓ Passed**MOT #10** 2018-04-26 11:45**MOT test number** 208657289832**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2017-04-19 16:23**MOT test number** 403331883368**Result** ✓ Passed**Advice** N/s/f anti rattle shim missing**Advice** O/s/f steering arm slight play**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2017-04-17 14:57**MOT test number** 578813067694**Result** ✗ Failed

- Advice** N/s/f anti rattle shim missing
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** O/s/f steering arm slight play
- Fail** Exhaust system not adequately supported front bracket (7.1.1)

MOT #7 2016-04-20 16:41**MOT test number** 394101089285**Result** ✓ Passed

- Advice** Nearside Front anti rattle clip missing

MOT #6 2016-04-12 08:38**MOT test number** 393339896427**Result** ✗ Failed

- Fail** Nearside Rear Trailing arm has excessive play in a pin/bush (2.4.G.2)
- Fail** Stop lamp not working (1.2.1b)
- Advice** Nearside Front anti rattle clip missing
- Fail** Offside Rear Trailing arm has excessive play in a pin/bush (2.4.G.2)

MOT #5 2015-04-16 15:00**MOT test number** 128106205100**Result** ✓ Passed**MOT #4** 2014-06-17 15:05**MOT test number** 678268464166**Result** ✓ Passed

**MOT #3** 2014-06-17 12:46**MOT test number** 835858864133**Result** ✗ Failed**Fail** Offside Rear Bonded suspension unit deteriorated and cannot function as intended (2.4.F.3)**Fail** Nearside Rear Bonded suspension unit deteriorated and cannot function as intended (2.4.F.3)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #2** 2013-06-10 12:15**MOT test number** 577051463134**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Power steering fluid level low, but not below minimum (2.3.1)**MOT #1** 2013-06-10 12:15**MOT test number** 299221463152**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Power steering fluid level low, but not below minimum (2.3.1)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
8 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	8 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-23
Last registration	2023-07-06
Complete history	See info



Registration #1	2010-06-23	18 mi
Registration #2	2013-06-10	32.671 mi
Registration #3	2014-06-17	43.138 mi
Registration #4	2014-06-17	43.138 mi
Registration #5	2015-04-16	51.080 mi
Registration #6	2016-04-12	58.606 mi
Registration #7	2016-04-20	58.606 mi
Registration #8	2017-04-17	64.951 mi
Registration #9	2017-04-19	64.988 mi
Registration #10	2019-06-20	75.377 mi
Registration #11	2019-06-20	75.377 mi
Registration #12	2019-06-20	75.377 mi
Registration #13	2019-06-20	75.377 mi
Registration #14	2019-06-20	75.377 mi
Registration #15	2019-06-20	75.377 mi
Registration #16	2019-06-20	75.377 mi
Registration #17	2019-06-20	75.377 mi
Registration #18	2019-06-20	75.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1733 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	AB66414
---------------	---------