



BG67ZKB

report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | SUZUKI |
| Model | VITARA SZ-T |
| Colour | Red |
| Year of manufacture | 2017 |
| Top speed | 112 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 118 BHP |
| Max. torque | 156 Nm at 4.400 rpm |
| Engine capacity | 1.586 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 123 g/km |
| CO2 label | D |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-04 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-12-16 |
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 6 |
| Total items failed | 5 |

| | |
|-------------------------|--|
| MOT #6 | 2023-12-11 10:04 |
| MOT test number | 299129518293 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-16 |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 2mm on outside edge (5.2.3 (e)) |
| Advice | Front Brake pad(s) wearing thin Approx 80% worn (1.1.13 (a) (ii)) |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|------------------------|---|
| MOT #5 | 2022-12-06 14:39 |
| MOT test number | 557216999702 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|------------------------|------------------|
| MOT #4 | 2021-12-14 12:10 |
| MOT test number | 456197642042 |
| Result | ✓ Passed |

**MOT #3** 2021-12-14 12:10**MOT test number** 345265376748**Result** ✗ Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2020-12-17 13:38**MOT test number** 200231402387**Result** ✓ Passed**MOT #1** 2020-12-16 10:32**MOT test number** 832841915425**Result** ✗ Failed

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Fail Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
16 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 305 |
| MOT expiry date | 16 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2017-11-17 |
| Last registration | 2023-12-11 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2017-11-17 | 25 mi |
| Registration #2 | 2020-12-16 | 17.962 mi |
| Registration #3 | 2020-12-17 | 17.962 mi |
| Registration #4 | 2020-12-17 | 17.962 mi |
| Registration #5 | 2020-12-17 | 17.962 mi |
| Registration #6 | 2020-12-17 | 17.962 mi |
| Registration #7 | 2020-12-17 | 17.962 mi |
| Registration #8 | 2020-12-17 | 17.962 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 85% |
| Pedestrian | 76% |
| Safety systems | 75% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1775 mm |
| Height | 1610 mm |
| Length | 4175 mm |
| Wheel base | 2500 mm |
| Kerb weight | 1150 kg |
| Max. allowed weight | 1730 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 47 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number | M16A-2091179 |