



report date: 2024-03-28

General information

| | |
|---------------------|-----------------|
| Make | HONDA |
| Model | CIVIC I-DTEC SE |
| Colour | Silver |
| Year of manufacture | 2013 |
| Top speed | 129 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 118 BHP |
| Max. torque | 300 Nm at 2.000 rpm |
| Engine capacity | 1.597 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 70.6 mpg |
| Consumption extra urban | 85.6 mpg |
| Consumption combined | 78.5 mpg |
| CO2 emission | 94 g/km |
| CO2 label | A |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-04 |
| Pictures | 39 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-14 |
| MOT pass rate | 89 % |
| MOT passed | 8 |
| Failed MOT tests | 1 |
| Total advice items | 16 |
| Total items failed | 1 |

| | |
|------------------|------------------|
| MOT #9 | 2023-05-23 09:52 |
| MOT test number | 177667268103 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-14 |

| | |
|-----------------|------------------|
| MOT #8 | 2022-05-16 13:22 |
| MOT test number | 649334394919 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #7 | 2021-06-15 15:27 |
| MOT test number | 246414972395 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #6 | 2020-06-10 09:48 |
| MOT test number | 940426817720 |
| Result | ✓ Passed |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Valve stem slightly damaged (5.2.3 (j)) |
| Advice | Nearside Front Valve stem slightly damaged (5.2.3 (j)) |

**MOT #5** 2020-06-09 13:46**MOT test number** 119352082586**Result** ✗ Failed

- Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Valve stem slightly damaged (5.2.3 (j))

MOT #4 2019-06-17 15:20**MOT test number** 610585191736**Result** ✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing Both tyres cracking (5.2.3 (d) (ii))

MOT #3 2019-01-07 11:37**MOT test number** 303597066438**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #2 2018-01-09 11:30**MOT test number** 285323657535**Result** ✓ Passed

- Advice** Engine bay covers fitted obscuring examinable components
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Under trays fitted obscuring examinable components



| | |
|-----------------|--|
| MOT #1 | 2016-12-13 14:17 |
| MOT test number | 537534447877 |
| Result | ✓ Passed |
| Advice | Engine covers fitted obscuring examinable components |
| Advice | Under trays fitted obscuring examinable components |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
14 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 32 |
| MOT expiry date | 14 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this HONDA had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2013-12-31 |
| Last registration | 2023-05-23 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-12-31 | 27 mi |
| Registration #2 | 2016-12-13 | 32.380 mi |
| Registration #3 | 2018-01-09 | 42.894 mi |
| Registration #4 | 2019-01-07 | 52.776 mi |
| Registration #5 | 2019-06-17 | 57.131 mi |
| Registration #6 | 2020-06-09 | 64.197 mi |
| Registration #7 | 2020-06-09 | 64.197 mi |
| Registration #8 | 2020-06-09 | 64.197 mi |
| Registration #9 | 2020-06-09 | 64.197 mi |
| Registration #10 | 2020-06-09 | 64.197 mi |
| Registration #11 | 2020-06-09 | 64.197 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 94% |
| Children | 83% |
| Pedestrian | 69% |
| Safety systems | 86% |
| Overall rating | 86% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2065 mm |
| Height | 1470 mm |
| Length | 4300 mm |
| Wheel base | 2697 mm |
| Kerb weight | 1428 kg |
| Max. allowed weight | 1870 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | N16A11008235 |