





# General information

Make	CITROEN
Model	C2 DESIGN
Colour	Silver
Year of manufacture	-
Top speed	105 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg





Internet history		
Entry 1		
Date	2021-10-12	
Pictures	0	
Listing price	View report	

source: autotrader.co.uk



## MOT history

MOT #19	2020-11-27 14:53
MOT test number	653372831651
Result	✓ Passed
Advice       Oil leak, but not excessive (8.4.1 (a) (i))         Advice       Front Suspension arm pin or bush worn but not resulting in excessive arm bushes starting to crack/split. (5.3.4 (a) (i))	2021-12-07 movement Both Nsf & Osf
MOT #18	2020-11-27 11:35
MOT test number	205961152520
Result	🗙 Failed
<b>Advice</b> Front Suspension arm pin or bush worn but not resulting in excessive movement Both Nsf & Osf arm bushes starting to crack/split. (5.3.4 (a) (i))	

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17		2019-11-29 09:10
MOT test	number	403353725732
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Inside bonnet cable loose of holder	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	



report date: 2024-03-29

MOT #16			2019-11-29 09:10
MOT test	number		571408662135
Result			🗙 Failed
Advice	Nearside Rear Di	rection indicator slightly discoloured (4.4.3 (a))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))			
Pass wit	h rectification	Bonnet cannot be secured in the closed position $(3.1 (b) (i))$	
Advice Oil leak, but not excessive (8.4.1 (a) (i))			
Advice Inside bonnet cable loose of holder			

MOT #15	2018-12-08 10:22
MOT test number	400477514518
Result	✓ Passed

MOT #14	2017-12-07 12:10
MOT test number	877624337078
Result	✓ Passed

MOT #13	2016-12-02 11:49
MOT test number	283604533422
Result	✓ Passed
Advice Slight wear in front brake discs	

MOT #12	2015-12-07 10:29
MOT test number	922654206093
Result	✓ Passed
Advice Slight wear in front discs	





MOT #11	2014-12-08 16:03
MOT test number	897052844342
Result	✓ Passed
MOT #10	2014-12-05 11:12
MOT test number	186569734315
Result	🗙 Failed
Fail         Offside Front position lamp(s) not working (1.1.A.3b)	
FailOffside rear brake binding (3.7.B.1)	
FailNearside Front coil spring broken (2.4.C.1a)	
Advice Offside Front coil spring corroded (2.4.C.1b)	
Notice N/s rear axle bump stop missing	

МОТ #9	2013-12-04 14:27
MOT test number	389158433350
Result	✓ Passed

МОТ #8	2013-11-26 14:19
MOT test number	558600733399
Result	🗙 Failed
Fail         Radius arm has excessive play in a ball joint (2.4.G.2)	

MOT #7	2013-05-01 14:11
MOT test number	197271823154
Result	✓ Passed
Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	



WU55UCP report date: 2024-03-29

МОТ #6		2013-05-01 14:11
MOT test number		799371123130
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
Advice Offside Rear Dir	ection indicator slightly discoloured (1.4.A.2f)	
Pass with rectification	Offside Headlamp aim too low (1.8)	
MOT #5		2012-05-01 18:08
MOT test number		539452422101
Result		✓ Passed
MOT #4		2012-04-30 15:50
MOT test number		315411422104
Result		🗙 Failed
Fail         Front Brake pad(s)	less than 1.5 mm thick (3.5.1g)	
Fail Parking brake: effic	iency below requirements (3.7.B.7)	
Fail Nearside rear parki	ng brake recording little or no effort (3.7.B.6a)	

FailNearside Rear Stop lamp not working (1.2.1b)

FailRear Registration plate lamp not working (1.1.C.1d)

FailNearside rear brake binding (3.7.B.1)

FailRear Parking brake lever has no reserve travel (3.1.6b)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)

**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)





МОТ #3	2010-10-25 14:14
MOT test number	272948690232
Result	✓ Passed
MOT #2	2010-10-25 12:07
MOT test number	402538290236
Result	🗙 Failed
<b>Fail</b> Offside Front Headlamp not working on dipped beam (1.7.5a)	
Fail         Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail         Offside Rear Stop lamp not working (1.2.1b)	
Fail         Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #1	2009-03-10 13:24
MOT test number	812559269030
Result	✓ Passed





## Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	······································
Category	AMP
Туре	

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-10-12
Last registration	2020-11-27
Complete history	<u>See info</u>



Registration #1	2005-10-12	6 mi
Registration #2	2009-03-10	32.437 mi
Registration #3	2010-10-25	41.537 mi
Registration #4	2010-10-25	41.537 mi
Registration #5	2012-04-30	51.674 mi
Registration #6	2012-05-01	51.674 mi
Registration #7	2013-05-01	55.867 mi
Registration #8	2013-11-26	58.236 mi
Registration #9	2013-12-04	58.238 mi
Registration #10	2014-12-05	62.823 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		01.207 est
Registration #19		11.777 mi
Registration #20		11.117 mi





Safety ratings

NCAP rating

Video

see crash video

Dimensions & weight	
Width	1659 mm
Height	1474 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	991 kg
Max. allowed weight	1362 kg
Additional information	
Additional information Fuel tank capacity	41
	41 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 3