



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D DRIVE SE LUX
Colour	White
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B






Internet history

Entry 1

Date	2022-05-20
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-15
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	25
Total items failed	9

MOT #16	2023-06-16 13:44
MOT test number	979107169584
Result	✓ Passed
Next expiry date	2024-06-15
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #15	2023-06-13 13:22
MOT test number	581951491070
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #14	2022-06-15 15:52
MOT test number	428365037213
Result	✓ Passed

**MOT #13** 2021-10-13 14:48**MOT test number** 477789172497**Result** ✓ Passed**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge slight inner edge wear (5.2.3 (e))**MOT #12** 2021-10-13 08:50**MOT test number** 258129460070**Result** ✗ Failed**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Front Tyre inner edge wear.**Advice** Offside Front Tyre worn close to legal limit/worn on edge Badly worn on inner edge. Perished and cracked. (5.2.3 (e))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure 205/50/17. (5.2.3 (d) (ii))**MOT #11** 2020-10-28 15:00**MOT test number** 292304281580**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #10** 2019-09-06 11:27**MOT test number** 505701802604**Result** ✓ Passed

**MOT #9** 2019-09-03 13:26**MOT test number** 364622343773**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Fail** Headlamp aim too low Nearside + Offside. (4.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Headlamp levelling device inoperative (4.1.5 (a))**MOT #8** 2018-10-04 15:40**MOT test number** 596524044867**Result** ✓ Passed**Advice** Front tyres wearing on edges**Advice** Nearside Rear Nail in tyre**MOT #7** 2018-10-04 12:19**MOT test number** 271599476983**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front tyres wearing on edges**MOT #6** 2017-10-03 09:44**MOT test number** 898341030859**Result** ✓ Passed

**MOT #5** 2016-09-30 12:42**MOT test number** 349925936998**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Metal in nearside rear tyre**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #4** 2016-09-30 12:42**MOT test number** 854182452890**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Metal in nearside rear tyre**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #3** 2015-10-05 10:04**MOT test number** 302452022712**Result** ✓ Passed**MOT #2** 2014-10-02 09:34**MOT test number** 326725674437**Result** ✓ Passed**Notice** Oil leak**MOT #1** 2013-09-20 11:55**MOT test number** 936233463207**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
15 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-14
Last registration	2023-06-16
Complete history	See info



Registration #1	2010-09-14	7 mi
Registration #2	2013-09-20	32.262 mi
Registration #3	2014-10-02	43.436 mi
Registration #4	2015-10-05	51.381 mi
Registration #5	2016-09-30	57.468 mi
Registration #6	2016-09-30	57.468 mi
Registration #7	2017-10-03	62.734 mi
Registration #8	2018-10-04	67.558 mi
Registration #9	2018-10-04	67.558 mi
Registration #10	2019-06-20	68.337 mi
Registration #11	2019-06-20	68.337 mi
Registration #12	2019-06-20	68.337 mi
Registration #13	2019-06-20	68.337 mi
Registration #14	2019-06-20	68.337 mi
Registration #15	2019-06-20	68.337 mi
Registration #16	2019-06-20	68.337 mi
Registration #17	2019-06-20	68.337 mi
Registration #18	2019-06-20	68.337 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602