



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CARINA GLI
Colour	Blue
Year of manufacture	1994
Top speed	110 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	106 BHP
Max. torque	135 Nm at 4.800 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-23
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-01-24
MOT pass rate	58 %
MOT passed	15
Failed MOT tests	11
Total advice items	52
Total items failed	40

MOT #26	2021-01-15 10:47
MOT test number	971896732435
Result	✓ Passed
Next expiry date	2022-01-24
Advice	Front registration plate delaminated but unlikely to be misread
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Washer jets not operating

MOT #25	2019-07-09 07:36
MOT test number	822242579920
Result	✓ Passed
Advice	Slight play in nearside front wheel bearing
Advice	Oil level low
Advice	Wipers cleaning poorly

MOT #24	2018-07-04 15:14
MOT test number	322061673370
Result	✓ Passed

**MOT #23**

2018-07-04 09:35

MOT test number

442428318301

Result

✗ Failed

Fail

Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

Fail

Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

MOT #22

2017-07-22 08:34

MOT test number

980625542799

Result

✓ Passed

Advice

Nearside Front Inner Track rod end ball joint has slight play (2.2.B.1f)

Advice

Engine management light on

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Steering column top bearing slightly worn (2.1.2c)

Advice

Drivers door outer moulding sticking out

Advice

Offside Front Inner Track rod end ball joint has slight play (2.2.B.1f)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #21

2016-07-13 06:47

MOT test number

124906245043

Result

✓ Passed

Advice

Nearside Front wheel bearing has slight play (2.5.A.3c)

MOT #20

2015-07-15 08:46

MOT test number

249976395493

Result

✓ Passed

**MOT #19** 2014-07-10 11:45**MOT test number** 685401894120**Result** ✓ Passed**MOT #18** 2014-07-05 11:28**MOT test number** 268856584482**Result** ✗ Failed

- Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Water leak from rad

MOT #17 2013-07-24 15:37**MOT test number** 995705903296**Result** ✓ Passed

- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)

**MOT #16**

2013-07-24 12:13

MOT test number

386195903488

Result**✗ Failed**

- Fail** Nearside Front Steering rack insecure (2.2.B.1a)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)
- Fail** Headlamp aim too low (1.8)
- Fail** Offside Front Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #15

2013-07-22 11:03

MOT test number

519693203226

Result**✗ Failed**

- Fail** Nearside Power steering ram(s) leaking from a failed seal (2.3.3b)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Headlamp aim too high (1.8)

**MOT #14**

2012-07-17 14:45

MOT test number

855579692138

Result

✓ Passed

- Notice** Advise offsidefront tyre getting low
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)
- Notice** Advise offside door trims sharp edges
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)

MOT #13

2012-07-12 12:00

MOT test number

566074192136

Result

✗ Failed

- Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)
- Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)
- Notice** Advise offsidefront tyre getting low
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Fail** Rear registration plate deteriorated (6.3.1d)
- Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)
- Notice** Advise offside door trims sharp edges
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)
- Fail** Nearside Windscreen wiper not operating automatically when switched on (8.2.1b)

**MOT #12** 2011-07-20 15:30**MOT test number** 478381901201**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #11** 2011-07-14 10:48**MOT test number** 847455891191**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Emissions not tested (7.0)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #10** 2010-07-08 15:49**MOT test number** 920909680146**Result** ✓ Passed

**MOT #9** 2010-07-07 12:52**MOT test number** 444008480185**Result** ✗ Failed**Fail** Offside front brake binding (3.7.B.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Offside Headlamp aim too high (1.8)**MOT #8** 2009-07-16 09:31**MOT test number** 623847999173**Result** ✓ Passed**MOT #7** 2009-07-15 13:04**MOT test number** 372766499137**Result** ✗ Failed**Fail** Nearside Headlamp not in good working order adversely affecting beam image (1.2.4a)**Fail** Emissions not tested (7.0)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Direction indicator incorrect colour (1.4.A.2f)**Notice** Advise water pump noisy and leaking**MOT #6** 2008-07-25 14:22**MOT test number** 720867708236**Result** ✓ Passed**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Advice** Offside Front brake disc slightly pitted (3.5.1h)

**MOT #5** 2008-07-11 15:02**MOT test number** 530043598193**Result** ✗ Failed**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Front Front wheel bearing has excessive play (2.5.A.3c)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front Front wheel bearing has excessive play (2.5.A.3c)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2007-05-16 09:35**MOT test number** 224066237419**Result** ✓ Passed**MOT #3** 2007-05-02 11:29**MOT test number** 830082927191**Result** ✗ Failed**Fail** Nearside Windscreen wiper blade deteriorated (8.2.2)**Fail** Nearside Front wheel bearing has excessive play (2.5.A.3c)



MOT #2	2006-05-26 11:13
MOT test number	264476846416
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2006-05-24 11:30
MOT test number	163544846171
Result	✗ Failed
Fail	Nearside Headlamp insecure (1.7.3)
Fail	Offside Stop lamp not working (1.2.1b)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Headlamp not in good working order adversely affecting beam image (1.2.4a)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✕
Untaxed

Tax expired:
1 October 2021

✕
MOT

Expired:
24 January 2022

Tax status	Expired at 1 October 2021
Days left	941 days too late
MOT expiry date	24 January 2022
Full MOT history	See MOT history



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	1994-10-18
Last registration	2021-01-15
Complete history	See info



Registration #1	1994-10-18	8 mi
Registration #2	2006-05-24	79.687 mi
Registration #3	2006-05-26	79.740 mi
Registration #4	2007-05-02	92.756 mi
Registration #5	2007-05-16	92.756 mi
Registration #6	2008-07-11	103.771 mi
Registration #7	2008-07-25	103.771 mi
Registration #8	2009-07-15	108.481 mi
Registration #9	2009-07-16	108.481 mi
Registration #10	2010-07-07	110.582 mi
Registration #11	2010-07-08	110.582 mi
Registration #12	2011-07-14	113.465 mi
Registration #13	2011-07-20	113.465 mi
Registration #14	2012-07-12	117.304 mi
Registration #15	2013-05-20	121.277 mi
Registration #16	2013-05-20	121.277 mi
Registration #17	2013-05-20	121.277 mi
Registration #18	2013-05-20	121.277 mi
Registration #19	2013-05-20	121.277 mi
Registration #20	2013-05-20	121.277 mi
Registration #21	2013-05-20	121.277 mi
Registration #22	2013-05-20	121.277 mi
Registration #23	2013-05-20	121.277 mi
Registration #24	2013-05-20	121.277 mi
Registration #25	2013-05-20	121.277 mi
Registration #26	2013-05-20	121.277 mi

Registration #27	2025-05-20	25,000,000
Registration #28	2025-05-20	25,000,000

[More info >](#)



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	4AB501006