





report date: 2024-03-29

General information

M. L.	BENIALILE
Make	RENAULT
Model	SCENIC DYNAMIQUE VVT 111 SCENIC
Colour	Blue
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-02

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT #21 2022-06-17 12:20

MOT test number 612051574528

Result

Passed

Next expiry date 2023-06-20

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20 2022-06-16 13:56

MOT test number 318144274587

Result X Failed

Fail Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #19 2021-06-21 13:54

MOT test number 751263031923

Result ✓ Passed **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Front Macpherson strut modified but not seriously weakened top (5.3.3 (c) (i)) Offside Front Play in steering rack inner joint(s) Advice Advice Brake pad(s) wearing thin rear both sides (1.1.13 (a) (ii)) Offside Rear Service brake binding but not excessively (1.2.1 (f)) Advice Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Oil leak, but not excessive engine (8.4.1 (a) (i)) Advice Nearside Front Play in steering rack inner joint(s) Brake pad(s) wearing thin front both sides (1.1.13 (a) (ii)) Advice Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f)) **Advice** Service brake requirements only just met. It would appear that the braking system requires adjustment or repair rear (1.2.1 (c))

2020-06-09 12:50 **MOT #18**

MOT test number 581458986626

Result ✓ Passed **Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Tyre slightly damaged/cracking or perishing both fronts (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



all lamps (4.7.1 (b) (ii))

FH07VHU

report date: 2024-03-29

MOT #17 2020-06-09 10:57

MOT test number 270909069558

Result X Failed

Fail Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Tyre slightly damaged/cracking or perishing both fronts (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Inner Steering linkage ball joint has excessive play rack (2.1.3 (b) (i))

Advice Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #16 2019-05-09 08:02

MOT test number 604205054273

Result ✓ Passed

MOT #15 2019-05-09 08:02

MOT test number 178559814361

Result X Failed

Pass with rectification Nearside Rear Registration plate lamp inoperative in the case of a single lamp or

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

MOT #14 2018-08-07 10:54

MOT test number 386910476556

Result \rightarrow Passed

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2017-08-02 08:43

MOT test number 842084477286

Result
✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #12		2017-08-02 08:43
MOT test number		564649210043
Result		× Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	

MOT #11	2016-08-13 09:49
MOT test number	195028553796
Result	✓ Passed
MOT #10	2016-08-13 09:00
MOT test number	712949511991
Result	X Failed
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	

MOT #9	2015-08-18 00:16
MOT test number	334117738865
Result	✓ Passed
MOT #8	2015-08-18 00:00
MOT test number	404178304489
Result	✓ Passed
MOT #7	2014-08-15 10:00
MOT test number	236787424201
Result	✓ Passed
MOT #6	2013-08-19 09:46

MOT #6	2013-08-19 09:46
MOT test number	129001833221
Result	√ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-29

MOT #5 2012-08-20 16:28 **MOT test number** 667323632204 Result ✓ Passed MOT #4 2012-08-20 09:29 **MOT** test number 395143132265 Result × Failed Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) **Notice** Front pads getting low Nearside Headlamp not working on dipped beam (1.7.5a) Fail

MOT #3

MOT test number

529022031215

Result

✓ Passed

MOT #2

2011-08-20 10:56

MOT test number

427712831276

Result

✓ Pass with rectification

Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #1	2010-08-19 15:25
MOT test number	110011730264
Result	✓ Passed

CarCheck.co.uk page 7/12




report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

Owner History	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-14
Last registration	2022-06-17
Complete history	See info



Registration #1	2007-06-14	16 mi
Registration #2	2010-08-19	23.880 mi
Registration #3	2011-08-20	28.676 mi
Registration #4	2012-08-20	33.786 mi
Registration #5	2012-08-20	33.786 mi
Registration #6	2013-08-19	39.162 mi
Registration #7	2014-08-15	43.637 mi
Registration #8	2015-08-18	47.626 mi
Registration #9	2015-08-18	47.626 mi
Registration #10	2016-08-13	51.711 mi
Registration #11	2016-08-13	51.711 mi
Registration #12		77,777 46
Registration #13		11.777 es
Registration #14		77,777 46
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		9.70 es
Registration #20		71.777 46
Registration #21		0.77 66
Registration #22		71.777 66

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2087 mm
Height	1701 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles2Engine numberD042546