





General information

Make	MERCEDES
Model	CLK CLK320 FINAL EDITION
Colour	Black
Year of manufacture	2002
Top speed	147 mph
0 - 60 mph	7.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	218 BHP
Max. torque	310 Nm at 3.000 rpm
Engine capacity	3.199 сс
Cylinders	6
Fuel type	Petrol
Consumption city	17.5 mpg
Consumption extra urban	35.8 mpg
Consumption combined	25.7 mpg
CO2 emission	266 g/km
CO2 label	Μ







Internet history


Entry 1

Date Pictures 2021-07-25

26

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-08-17
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	36
Total items failed	4

MOT #20	2022-08-16 10:10
MOT test number	108213050363
Result	✓ Passed
Next expiry date	2023-08-17

MOT #19	2021-07-27 14:04
MOT test number	656358110881
Result	✓ Passed

MOT #18	2020-08-18 14:32
MOT test number	928327554928
Result	✓ Passed

MOT #17		2019-08-12 09:07
MOT test	number	402885385708
Result		✓ Passed
Advice	Exhaust joints corroded	
Advice	Engine/under trays fitted	
Advice	O/s sill panel suspect under plastic cover could be corroded	





MOT #16	2018-08-15 09:44
MOT test number	816078636102
Result	✓ Passed
Advice Engine/under trays fitted	
MOT #15	2017-08-17 10:16
MOT test number	688257959522
Result	✓ Passed
Advice Engine/under trays fitted	
Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Brake pad(s) wearing thin (3.5.1g)	

MOT #14		2016-08-18 08:10
MOT test number		989252456822
Result		✓ Passed
Advice Engine	/under trays fitted	
Advice Front E	Brake pad(s) wearing thin both sides (3.5.1g)	

MOT #13	2016-08-16 11:55
MOT test number	296668110766
Result	× Failed
Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Engine/under trays fitted	
Advice Front Brake pad(s) wearing thin both sides (3.5.1g)	
Fail Offside Headlamp not working on dipped beam (1.7.5a)	



KN02ZSG report date: 2024-03-29

MOT #12		2015-08-10 14:32
MOT test nur	mber	378672525247
Result		✓ Passed
	ffside Front Front wheel bearing has slight play (2.5.A.3c) earside Front Front wheel bearing has slight play (2.5.A.3c)	

MOT #11		2015-08-10 14:32
MOT test number		855742025220
Result		🗙 Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)	
Advice Offside Front Front wheel bearing has slight play (2.5.A.3c)		
Advice Nearside Front Front wheel bearing has slight play (2.5.A.3c)		

MOT #10		2014-08-18 14:45
MOT test	number	385990834494
Result		🗸 Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

MOT #9		2013-08-15 09:44
MOT test	number	468767623274
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	





MOT #8	2012-08-15 10:48
MOT test number	987828222284
Result	✓ Passed
NoticeEngine covers fitted obscuring some components in the engine bayNoticeFront x2 tyres worn on inside/outside treads	

MOT #7		2011-07-29 15:06
MOT test	number	865040011254
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

МОТ #6	2011-07-29 11:00
MOT test number	486480911243
Result	🗙 Failed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5		2010-08-10 10:52
MOT test	number	570082620217
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Brake pipes above fuel tank not checked	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	



KN02ZSG report date: 2024-03-29

> 2008-06-16 11:50 520898468129

MOT #4		2009-08-18 11:03
MOT test	number	660860839299
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3

мот	test	num	ber	

Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice adjustmen	Brakes imbalanced requirements only just met. It would appear that the braking system requires t or repair. (3.7.D.2c)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2	2007-06-04 10:48
MOT test number	582985957176
Result	✓ Passed
MOT #1	2006-06-13 11:08
MOT test number	640714066143

Result

Passed



Tax & MOT check

X Untaxed Tax expired: 1 January 2023	X MOT Expired: 17 August 2023
Tax status	Expired at 1 January 2023
Days left	484 days too late
MOT expiry date	17 August 2023
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	AMP
Туре	A CONTRACT
Damage 2	AMPLE
Date	
Category	AMPT
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



KN02ZSG report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2002-05-17
Last registration	2022-08-16
Complete history	<u>See info</u>



2002-05-17	16 mi
2006-06-13	47.981 mi
2007-06-04	55.918 mi
2008-06-16	61.762 mi
2009-08-18	67.367 mi
2010-08-10	70.972 mi
2011-07-29	72.158 mi
2011-07-29	72.182 mi
2012-08-15	73.399 mi
2013-08-15	74.806 mi
	11.777 est
	11.777 est
	11.777 esi
	11.777 est
	11.777 esi
	11.777 est
	11.777 esi
	11.117 est
	11.777 mi
	2006-06-13 2007-06-04 2008-06-16 2009-08-18 2010-08-10 2011-07-29 2011-07-29 2012-08-15 2013-08-15





Dimensions & weight

Width	1722 mm
Height	1345 mm
Length	4567 mm
Wheel base	2690 mm
Kerb weight	1420 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11294031365453