



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Silver
Year of manufacture	2004
Top speed	100 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	81 BHP
Max. torque	117 Nm at 3.200 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-05-22
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-14
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	15
Total items failed	13

MOT #20	2023-11-18 17:03
MOT test number	236198590052
Result	✓ Passed
Next expiry date	2024-12-14
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19	2023-11-18 13:42
MOT test number	554294271850
Result	✗ Failed
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Emissions unable to be completed exhaust blowing (8.2.1.2 (d))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #18** 2022-12-15 11:20**MOT test number** 253691872539**Result** ✓ Passed**Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Offside Rear Outer Prop shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Central Front Exhaust has a minor leak of exhaust gases center pipe miner leak (6.1.2 (a))**MOT #17** 2021-08-26 10:20**MOT test number** 255735894040**Result** ✓ Passed**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #16** 2020-09-12 10:37**MOT test number** 745708666883**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #15** 2019-09-18 10:01**MOT test number** 449387268254**Result** ✓ Passed**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge AND OUTER (5.2.3 (e))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge AND OUTER (5.2.3 (e))

**MOT #14** 2018-09-10 15:29**MOT test number** 653006663249**Result** ✓ Passed**MOT #13** 2018-02-09 15:36**MOT test number** 734330692816**Result** ✓ Passed**MOT #12** 2018-02-09 15:36**MOT test number** 486979936375**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #11** 2017-02-24 12:59**MOT test number** 107458916153**Result** ✓ Passed**MOT #10** 2017-02-24 12:59**MOT test number** 667126444923**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #9** 2016-02-29 11:10**MOT test number** 764152509317**Result** ✓ Passed



MOT #8	2015-02-01 15:23
---------------	------------------

MOT test number	566012735094
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2013-11-11 10:12
---------------	------------------

MOT test number	267145413382
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2012-11-05 15:32
---------------	------------------

MOT test number	218010312389
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2011-11-08 13:50
---------------	------------------

MOT test number	878882811379
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2010-11-03 15:40
---------------	------------------

MOT test number	270707700398
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2009-11-13 11:39
---------------	------------------

MOT test number	304887119315
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	All tyres cracking to side wall areas
---------------	---------------------------------------

Advice	Front Brake pad(s) wearing thin (3.5.1g)
---------------	--

MOT #2	2008-09-02 10:36
---------------	------------------

MOT test number	684366848263
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2007-09-03 11:07
MOT test number	170496147212
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
14 December 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	14 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EU54OZR
Plate since	2019-03-29
Current registration	EU54OZR
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-09-01
Last registration	2023-11-18
Complete history	See info



Registration #1	2004-09-01	21 mi
Registration #2	2007-09-03	13.206 mi
Registration #3	2008-09-02	16.698 mi
Registration #4	2009-11-13	19.248 mi
Registration #5	2010-11-03	21.211 mi
Registration #6	2011-11-08	23.447 mi
Registration #7	2012-11-05	26.882 mi
Registration #8	2013-11-11	30.140 mi
Registration #9	2015-02-01	32.561 mi
Registration #10	2016-02-29	41.623 mi
Registration #11	2017-02-24	49.676 mi
Registration #12	2018-02-29	55.277 mi
Registration #13	2019-02-29	55.277 mi
Registration #14	2020-02-29	55.277 mi
Registration #15	2021-02-29	55.277 mi
Registration #16	2022-02-29	55.277 mi
Registration #17	2023-02-29	55.277 mi
Registration #18	2023-02-29	55.277 mi
Registration #19	2023-02-29	55.277 mi
Registration #20	2023-02-29	55.277 mi
Registration #21	2023-02-29	55.277 mi
Registration #22	2023-02-29	55.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1125 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	64EA4559305