



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 SPORT
Colour	White
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-11-07
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-10-19
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	43
Total items failed	5

MOT #17	2023-10-05 14:22
MOT test number	868878300947
Result	✓ Passed
Next expiry date	2024-10-19

MOT #16	2023-10-05 09:59
MOT test number	302535660637
Result	✗ Failed
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
MAJOR	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #15	2022-10-06 09:49
MOT test number	705834492279
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Both rear tyres wearing uneven
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #14**

2021-09-27 11:39

**MOT test number**

906141724439

**Result**

✓ Passed

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice**

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13**

2020-10-09 14:43

**MOT test number**

567431663238

**Result**

✓ Passed

**MOT #12**

2019-10-04 08:56

**MOT test number**

654663070119

**Result**

✓ Passed

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice**

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #11**

2018-10-11 09:21

**MOT test number**

127586593949

**Result**

✓ Passed

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor**

Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #10** 2018-10-04 10:45**MOT test number** 784366764094**Result** ✗ Failed**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9** 2017-10-05 09:45**MOT test number** 834666863323**Result** ✓ Passed**MOT #8** 2016-09-30 13:26**MOT test number** 781840610140**Result** ✓ Passed**Advice** Front registration plate cracked**Advice** Chips in screen**MOT #7** 2016-09-30 08:30**MOT test number** 482067177338**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit feathered and perished (4.1.E.1)**Advice** Chips in screen**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm feathered and perished (4.1.E.1)**Advice** Front registration plate cracked

**MOT #6**

2015-09-21 09:45

**MOT test number**

340437462397

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Chips in screen
- Advice** Nearside Front tyre wearing inner edge
- Advice** Offside Rear tyre perished and feathered inner edge
- Advice** Offside Front tyre low and worn thin inner edge
- Advice** Tracking toe out too much
- Advice** Nearside Rear tyre perished and getting low

**MOT #5**

2015-09-21 09:45

**MOT test number**

603591684688

**Result**

✗ Failed

- Advice** Offside Front tyre low and worn thin inner edge
- Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Tracking toe out too much
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear tyre perished and getting low
- Advice** Chips in screen
- Advice** Nearside Front tyre wearing inner edge
- Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Rear tyre perished and feathered inner edge

**MOT #4** 2014-10-01 16:31**MOT test number** 698574674282**Result** ✓ Passed**Advice** Nearside Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Nearside rear tyre starting to perish**Notice** Nearside side repeater lens cracked and holed**Notice** Chips in screen**Notice** Offside rear tyre starting to perish**MOT #3** 2014-10-01 12:28**MOT test number** 308634874474**Result** ✗ Failed**Advice** Nearside Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Nearside rear tyre starting to perish**Fail** Offside Headlamp aim too low (1.8)**Notice** Chips in screen**Notice** Offside rear tyre starting to perish**MOT #2** 2013-10-04 16:35**MOT test number** 297827373219**Result** ✓ Passed**MOT #1** 2012-10-05 17:29**MOT test number** 419109172268**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
19 October 2024

Tax status		Valid until 1 November
Days left		186
MOT expiry date		19 October 2024
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-10-19
Last registration	2023-10-05
Complete history	<a href="#">See info</a>



Registration #1	2009-10-19	16 mi
Registration #2	2012-10-05	19.920 mi
Registration #3	2013-10-04	23.355 mi
Registration #4	2014-10-01	29.118 mi
Registration #5	2014-10-01	29.118 mi
Registration #6	2015-09-21	37.630 mi
Registration #7	2015-09-21	37.630 mi
Registration #8	2016-09-30	45.778 mi
Registration #9	2016-09-30	45.778 mi
Registration #10	2017-10-05	51.644 mi
Registration #11	2018-10-05	51.644 mi
Registration #12	2018-10-05	51.644 mi
Registration #13	2018-10-05	51.644 mi
Registration #14	2018-10-05	51.644 mi
Registration #15	2018-10-05	51.644 mi
Registration #16	2018-10-05	51.644 mi
Registration #17	2018-10-05	51.644 mi
Registration #18	2018-10-05	51.644 mi
Registration #19	2018-10-05	51.644 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number	156670
---------------	--------