



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO EDGE 16V
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	170 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	37.2 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-17
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	47
Total items failed	20

MOT #22	2024-01-17 12:00
MOT test number	158072062557
Result	✓ Passed
Next expiry date	2025-01-17
Advice	Parking Brake lever has little reserve travel

MOT #21	2024-01-16 17:28
MOT test number	861623203201
Result	✗ Failed
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Parking Brake lever has little reserve travel

MOT #20	2023-01-18 10:28
MOT test number	181640609373
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19**

2023-01-16 12:48

MOT test number

218412873688

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Headlamp aim not tested (4.1.2 (b))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Headlamp levelling device inoperative (4.1.5 (a))
- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #18

2022-01-10 13:12

MOT test number

101080941934

Result**✓ Passed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17**

2022-01-08 09:34

MOT test number

535214460547

Result**✗ Failed**

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #16

2020-12-15 13:09

MOT test number

859089605622

Result**✓ Passed**

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15

2020-03-19 14:17

MOT test number

896355064284

Result**✓ Passed**

- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14**

2020-03-19 10:00

MOT test number

279333075104

Result**✗ Failed**

- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Front Heat shield loose and rattling.
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13

2019-03-27 14:45

MOT test number

484348136922

Result**✓ Passed**

- Advice** Front Suspension arm corroded but not seriously weakened both sides lower arm (5.3.3 (b) (i))
- Advice** Corrosion to rear axle

MOT #12

2019-03-27 12:47

MOT test number

585070713017

Result**✗ Failed**

- Advice** Corrosion to rear axle
- Fail** Front Registration plate inscription illegible damage to lettering (0.1 (b))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Suspension arm corroded but not seriously weakened both sides lower arm (5.3.3 (b) (i))

**MOT #11** 2018-03-31 12:19**MOT test number** 268034765151**Result** ✓ Passed**MOT #10** 2017-03-23 11:36**MOT test number** 579393031259**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Rear brake binding slightly.**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #9** 2017-03-16 15:29**MOT test number** 697227551493**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Power steering fluid level below minimum (2.3.1)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Rear brake binding slightly.**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Rear Tyre has ply or cords exposed outer sidewall (4.1.D.1b)**Fail** Offside Rear wheel bearing rough when rotated (2.6.1)

**MOT #8** 2016-03-24 13:37**MOT test number** 169739755978**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Rear brake binding slightly.**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #7** 2015-03-20 11:07**MOT test number** 945749475017**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2015-03-19 17:03**MOT test number** 978948175024**Result** ✗ Failed**Fail** Nearside Rear brake caliper leaking (3.6.A.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2014-03-05 11:42**MOT test number** 149934164045**Result** ✓ Passed**MOT #4** 2013-03-06 10:41**MOT test number** 838205963064**Result** ✓ Passed



MOT #3	2012-02-22 08:58
MOT test number	545643652037
Result	✓ Passed

MOT #2	2011-03-11 08:35
MOT test number	118070771408
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-03-18 11:19
MOT test number	980697670080
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
17 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-03-14
Last registration	2024-01-17
Complete history	See info



Registration #1	2007-03-14	27 mi
Registration #2	2010-03-18	11.575 mi
Registration #3	2011-03-11	21.337 mi
Registration #4	2012-02-22	31.685 mi
Registration #5	2013-03-06	39.620 mi
Registration #6	2014-03-05	43.196 mi
Registration #7	2015-03-19	46.342 mi
Registration #8	2015-03-20	46.342 mi
Registration #9	2016-03-24	49.603 mi
Registration #10	2017-03-16	53.305 mi
Registration #11	2017-03-23	53.370 mi
Registration #12	2018-03-31	57.288 mi
Registration #13	2019-03-20	61.217 mi
Registration #14	2019-03-20	61.217 mi
Registration #15	2019-03-20	61.217 mi
Registration #16	2019-03-20	61.217 mi
Registration #17	2019-03-20	61.217 mi
Registration #18	2019-03-20	61.217 mi
Registration #19	2019-03-20	61.217 mi
Registration #20	2019-03-20	61.217 mi
Registration #21	2019-03-20	61.217 mi
Registration #22	2019-03-20	61.217 mi
Registration #23	2019-03-20	61.217 mi
Registration #24	2019-03-20	61.217 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1812 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1375 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6A55622