



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	TIGRA SRI 16V
Colour	Black
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-27
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2022-09-08
<b>MOT pass rate</b>	74 %
<b>MOT passed</b>	14
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	64
<b>Total items failed</b>	23

**MOT #19** 2021-09-09 12:47**MOT test number** 104589641985**Result** Passed**Next expiry date** 2022-09-08**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #18** 2020-11-09 14:54**MOT test number** 384512833920**Result** Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #17

2019-05-07 16:07

MOT test number

769244291507

Result		✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material flexi to hub metal pipe corroded (1.1.11 (c))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material metal pipe to the flexi corroded (1.1.11 (c))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Various suspension parts corroded	
Advice	Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	

**MOT #16**

2019-05-07 09:51

**MOT test number**

938228410498

**Result****✗ Failed**

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material flexi to hub metal pipe corroded (1.1.11 (c))
- Advice** Various suspension parts corroded
- Fail** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material metal pipe to the flexi corroded (1.1.11 (c))

**MOT #15**

2018-05-22 13:04

**MOT test number**

486254953750

**Result**

✓ Passed

**Advice**

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice**

Vehicles internal headlight adjuster altered to recheck lights

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14**

2018-05-21 13:56

**MOT test number**

910468783725

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Bonnet cannot be secured in the closed position (3.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #13**

2017-05-25 09:12

**MOT test number**

860042283210

**Result****✓ Passed**

- Advice** Engine covers fitted obscuring some components in the engine bay
- Advice** Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)
- Advice** Nearside Front Tyre has slight cracking
- Advice** Fuel filter appears corroded
- Advice** Offside Rear Tyre has slight cracking in tread

**MOT #12**

2017-05-22 14:44

**MOT test number**

639862011208

**Result****✗ Failed**

**Advice** Central Exhaust has a minor leak of exhaust gases Exhaust corroded and leaking various places / rear silencer pipe corroded (7.1.2)

**Fail** Nearside Front Brake hose ferrule excessively corroded (3.6.B.4e)

**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)

**Advice** Engine covers fitted obscuring some components in the engine bay

**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)

**Advice** Battery hold down clamp not seated correctly

**Advice** Offside Rear Tyre has slight cracking in tread

**Fail** Nearside Rear coil spring broken (2.4.C.1a)

**Advice** Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

**Fail** Offside Front Brake hose ferrule excessively corroded (3.6.B.4e)

**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)

**Advice** Fuel filter appears corroded

**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Nearside Front Tyre has slight cracking

**MOT #11**

2016-06-06 10:16

**MOT test number**

887038817677

**Result****✓ Passed**

**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened edge (3.5.1i)

**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened edge (3.5.1i)





MOT #10	2016-06-06 10:16
MOT test number	389886465720
Result	✗ Failed
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)
Advice	Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened edge (3.5.1i)
Pass with rectification	Nearside Front Headlamp not working on dipped beam (1.7.5a)
Advice	Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened edge (3.5.1i)

MOT #9	2015-08-04 15:35
MOT test number	375916815401
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2015-08-04 13:45**MOT test number** 119596215245**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Rear Brake cable has wires broken and is significantly weakened (3.5.1b)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Rear Brake cable has wires broken and is significantly weakened (3.5.1b)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**MOT #7** 2014-07-31 10:39**MOT test number** 426082514299**Result** ✓ Passed**MOT #6** 2013-07-18 16:06**MOT test number** 698229693105**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside and offside tyres perrished



<b>MOT #5</b>	2012-07-25 18:15
<b>MOT test number</b>	348437802278
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2011-07-20 16:01
<b>MOT test number</b>	325651501213
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2010-07-21 15:17
<b>MOT test number</b>	594322900231
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2009-08-07 07:47
<b>MOT test number</b>	114009819247
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2008-07-28 08:56
<b>MOT test number</b>	630920818285
<b>Result</b>	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
9 April 2022

✕  
MOT

Expired:  
8 September 2022

Tax status	Expired at 9 April 2022
Days left	750 days too late
MOT expiry date	8 September 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>LA05DZY</b>
Plate since	2024-03-29
Current registration	 <b>LA05DZY</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-07-28
Last registration	2021-09-09
Complete history	<a href="#">See info</a>



Registration #1	2005-07-28	26 mi
Registration #2	2008-07-28	11.998 mi
Registration #3	2009-08-07	14.805 mi
Registration #4	2010-07-21	18.549 mi
Registration #5	2011-07-20	25.956 mi
Registration #6	2012-07-25	29.990 mi
Registration #7	2013-07-18	32.733 mi
Registration #8	2014-07-31	35.989 mi
Registration #9	2015-08-04	38.639 mi
Registration #10	2015-08-04	38.640 mi
Registration #11	2016-06-06	40.183 mi
Registration #12	2016-06-06	40.183 mi
Registration #13	2016-06-06	40.183 mi
Registration #14	2016-06-06	40.183 mi
Registration #15	2016-06-06	40.183 mi
Registration #16	2016-06-06	40.183 mi
Registration #17	2016-06-06	40.183 mi
Registration #18	2016-06-06	40.183 mi
Registration #19	2016-06-06	40.183 mi
Registration #20	2016-06-06	40.183 mi
Registration #21	2016-06-06	40.183 mi

More info >





Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1955 mm
Height	1440 mm
Length	3817 mm
Wheel base	2491 mm
Kerb weight	1133 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	19FC6425