



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SPORT
Colour	Blue
Year of manufacture	2008
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 2

Date	2021-09-11
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-10
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-29
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	12
Total items failed	0

MOT #16	2023-09-13 11:12
MOT test number	700621037024
Result	✓ Passed
Next expiry date	2024-09-29
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2023-09-13 08:32
MOT test number	859842555960
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-09-02 09:19
MOT test number	992209665033
Result	✓ Passed

MOT #13	2021-09-30 07:07
MOT test number	924308433365
Result	✓ Passed

**MOT #12** 2020-07-31 10:48**MOT test number** 296318860722**Result** ✓ Passed**MOT #11** 2020-07-31 08:10**MOT test number** 607979587659**Result** ✗ Failed**MAJOR** Exhaust system insecure front bracket broken (6.1.2 (a))**MOT #10** 2019-07-26 15:28**MOT test number** 700287811406**Result** ✓ Passed**MOT #9** 2018-07-20 08:30**MOT test number** 468112919911**Result** ✓ Passed**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Rear tyres wearing on edges**MOT #8** 2018-07-19 14:34**MOT test number** 864120036699**Result** ✗ Failed**Advice** Rear tyres wearing on edges**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))



MOT #7	2017-07-25 10:56
MOT test number	452198248636
Result	✓ Passed
Advice	Both rear tyres wearing slightly on inner edges
MOT #6	2016-08-09 11:48
MOT test number	503823064630
Result	✓ Passed
MOT #5	2015-07-28 08:14
MOT test number	281271705812
Result	✓ Passed
MOT #4	2014-08-12 11:20
MOT test number	228034424216
Result	✓ Passed
MOT #3	2013-08-16 09:32
MOT test number	766048423233
Result	✓ Passed
MOT #2	2012-08-18 09:55
MOT test number	338311832233
Result	✓ Passed
MOT #1	2011-10-03 13:28
MOT test number	666386471269
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
29 September 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-01
Last registration	2023-09-13
Complete history	See info



Registration #1	2008-09-01	9 mi
Registration #2	2011-10-03	15.473 mi
Registration #3	2012-08-18	22.183 mi
Registration #4	2013-08-16	27.499 mi
Registration #5	2014-08-12	34.055 mi
Registration #6	2015-07-28	36.473 mi
Registration #7	2016-08-09	40.005 mi
Registration #8	2017-07-25	42.036 mi
Registration #9	2018-07-19	44.174 mi
Registration #10	2018-07-20	44.174 mi
Registration #11	2019-05-20	51.277 mi
Registration #12	2019-05-20	51.277 mi
Registration #13	2019-05-20	51.277 mi
Registration #14	2019-05-20	51.277 mi
Registration #15	2019-05-20	51.277 mi
Registration #16	2019-05-20	51.277 mi
Registration #17	2019-05-20	51.277 mi
Registration #18	2019-05-20	51.277 mi
Registration #19	2019-05-20	51.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1289 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	153102