



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D3 SE LUX EDITION
Colour	Blue
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 2

Date	2024-02-16
Pictures	26
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-02
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-04
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	20
Total items failed	2

MOT #12	2023-06-19 14:21
MOT test number	453951840201
Result	✓ Passed
Next expiry date	2024-07-04
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11	2022-06-15 10:00
MOT test number	108440080867
Result	✓ Passed
Advice	Items removed from driver's view prior to test

MOT #10	2021-07-05 15:17
MOT test number	153571323527
Result	✓ Passed

MOT #9	2020-09-18 08:24
MOT test number	429750776036
Result	✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #8** 2019-09-11 08:20**MOT test number** 389540921843**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2018-09-12 15:31**MOT test number** 757804611577**Result** ✓ Passed**MOT #6** 2017-09-11 15:36**MOT test number** 508876300470**Result** ✓ Passed**MOT #5** 2016-09-13 14:45**MOT test number** 982990563889**Result** ✓ Passed

- Advice** Front tyres wearing on inner edge

**MOT #4** 2016-09-12 14:23**MOT test number** 125349146782**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front tyres wearing on inner edge**MOT #3** 2015-09-01 12:38**MOT test number** 886151251964**Result** ✓ Passed**MOT #2** 2014-09-09 12:03**MOT test number** 276752554205**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2014-09-09 12:03**MOT test number** 898172054217**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

X

Untaxed

Tax expired:  
3 February 2024

✓

MOT

Expires:  
4 July 2024

Tax status	Expired at 3 February 2024
Days left	85 days too late
MOT expiry date	4 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-28
Last registration	2023-06-19
Complete history	<a href="#">See info</a>



Registration #1	2011-09-28	23 mi
Registration #2	2014-09-09	24.788 mi
Registration #3	2015-09-01	31.626 mi
Registration #4	2016-09-12	37.608 mi
Registration #5	2016-09-13	37.608 mi
Registration #6	2017-09-11	44.087 mi
Registration #7	2018-09-12	52.498 mi
Registration #8	2019-09-09	55.277 mi
Registration #9	2019-09-09	55.277 mi
Registration #10	2019-09-09	55.277 mi
Registration #11	2019-09-09	55.277 mi
Registration #12	2019-09-09	55.277 mi
Registration #13	2019-09-09	55.277 mi
Registration #14	2019-09-09	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1561 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1033709