





report date: 2024-03-28

General information

Make	FIAT
Model	500C TWINAIR S
Colour	Black
Year of manufacture	2015
Top speed	117 mph
0 - 60 mph	10.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 2.000 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2022-04-12

Pictures 65

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-12
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	18
Total items failed	2

MOT #9		2024-03-12 09:46
MOT test	number	327039419019
Result		✓ Passed
Next expi	ry date	2025-03-12
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material Plastic casing lifting. (1.1.11 (c))		
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))		
Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))		
Advice Offside Rear Brake pipe corroded, covered in grease or other material Plastic casing lifting. (1.1.11 (c))		

CarCheck.co.uk page 3/12



 $(1.\overline{1.11} (c))$

DU15CTX

report date: 2024-03-28

2024-03-11 11:37 **MOT #8** 805589781007 **MOT** test number Result × Failed **Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall. (5.2.3 (d) (i)) Offside Front Shock absorbers has light misting of oil (5.3.2 (b)) **Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) **Advice** Advice Offside Rear Brake pipe corroded, covered in grease or other material Plastic casing lifting. (1.1.11(c))Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) Fail Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c)) **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Plastic casing lifting.

MOT #7		2023-03-10 10:16
MOT test	number	756481414280
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #6	2022-03-09 10:05
MOT test number	951633054844
Result	✓ Passed
MOT #5	2021-03-09 11:50
MOT test number	272751121385
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 4/12



MOT #4 2021-03-09 11:50

MOT test number 800988720987

Result X Failed

Pass with rectification Front Headlamp aim too low both front to low (4.1.2 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2020-03-06 10:16

MOT test number 856544422477

Result
✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge starting to wear on inside edge (5.2.3

(e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge starting to wear on inside edge (5.2.3

(e))

MOT #2 2019-03-08 09:33

MOT test number 389655351777

Result ✓ Passed

MOT #1 2018-03-05 17:56

MOT test number 661854750981

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	12 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

· ·		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I		e?

	More info	>
Plate changes See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-13
Last registration	2024-03-12
Complete history	See info



Registration #1	2015-03-13	26 mi
Registration #2	2018-03-05	13.428 mi
Registration #3	2019-03-08	16.444 mi
Registration #4	2020-03-06	20.120 mi
Registration #5	2021-03-09	23.567 mi
Registration #6	2021-03-09	23.567 mi
Registration #7		11.777 es
Registration #8		0.074
Registration #9		11.777 es
Registration #10		0.074
Registration #11		11.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1380 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number 0289135