





### General information

Make	VOLKSWAGEN
Model	POLO SE (79BHP)
Colour	Silver
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.400 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F





# MOT history

MOT expiry date	2021-12-27
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	13
Total items failed	7

MOT #13	2020-12-22 12:15
MOT test number	975296473280
Result	✓ Passed
Next expiry date	2021-12-27
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2019-12-04 14:18
MOT test number	411967996110
Result	✓ Passed

MOT #11	2018-12-28 15:53
MOT test number	869939091116
Result	✓ Passed

MOT #	10	2018-12-28 10:52
MOT te	est number	525777878251
Result		🗙 Failed
Fail	Offside Headlamp aim too low (4.1.2 (a))	
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail (ii))	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ing	press of dirt (5.3.4 (b)





МОТ #9	2017-12-27 16:02
MOT test number	825688588170
Result	✓ Passed
МОТ #8	2016-12-16 12:05
MOT test number	776769045171
Result	✓ Passed

МОТ #7	2015-10-26 11:43
MOT test number	439801819377
Result	✓ Passed
Advice Undertrays fitted	
Advice Item removed from drivers view	

МОТ #6	2014-10-20 14:07
MOT test number	636813394292
Result	✓ Passed
<b>Notice</b> Under-trays fitted obscuring some underside components	

MOT #5	2014-10-20 09:30	
MOT test number	758503194202	
Result	🗙 Failed	
<b>Notice</b> Under-trays fitted obscuring some underside components		
Fail         Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)		
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting i (2.4.G.2)	n excessive movement	





MOT #4	2013-10-29 13:39
MOT test number	438602603392
Result	✓ Passed
<b>Notice</b> Under-trays fitted obscuring some underside components	
MOT #3	2013-10-28 14:00
MOT test number	949141603355
Result	🗙 Failed
Fail         Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
<b>Notice</b> Under-trays fitted obscuring some underside components	
<b>Notice</b> Offside rear tyre has cuts on inner side wall	
Fail         Nearside Side repeater not working (1.4.A.2c)	
Fail         Offside Headlamp aim too low (1.8)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
<b>Notice</b> Offside front tyre has cuts on inner side wall	
Notice Nearside rear tyre outer side wall cracking	

MOT #2	2012-10-22 10:45
MOT test number	917836992239
Result	✓ Passed

MOT #1	2011-10-17 16:21
MOT test number	825120491213
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 26 January 2021	<b>X</b> <b>MOT</b> Expired: 27 December 2021
Tax status	Expired at 26 January 2021
Days left	1189 days too late
MOT expiry date	27 December 2021
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT ON
Date	*
Category	AMP
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
*********	
**********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Rumber of plates	,
Rumber of plates Carrent registration	
Rumber of plates Carrent registration Fals since	
Rumber of protes Current registration Current registration	
Rumber of plates Carrent registration Fate since Fate since Fate since	1000-20-20





### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-03-19
Last registration	2020-12-22
Complete history	See info



Registration #1	2008-03-19	23 mi
Registration #2	2011-10-17	14.623 mi
Registration #3	2012-10-22	20.909 mi
Registration #4	2013-10-28	25.843 mi
Registration #5	2013-10-29	25.843 mi
Registration #6	2014-10-20	32.639 mi
Registration #7	2014-10-20	32.639 mi
Registration #8		11.777 est
Registration #8 Registration #9		11.777 es
-		0.000 es
Registration #9		01,000 est 01,000 est 01,000 est 01,000 est
Registration #9 Registration #10		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est
Registration #9 Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est





## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1191 kg
Max. allowed weight	1580 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BUD512929