



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	LANDCRUISER D-4D LC4 8 SEATS
Colour	Black
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	164 BHP
Max. torque	410 Nm at 2.000 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	243 g/km
CO2 label	L






Internet history

Entry 1

Date	2022-02-21
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-04
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	47
Total items failed	13

MOT #22	2024-04-05 15:47
MOT test number	973620472136
Result	✓ Passed
Next expiry date	2025-04-04
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #21	2024-04-05 11:08
MOT test number	157654025131
Result	✗ Failed
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #20**

2023-04-05 14:50

**MOT test number**

260420696636

**Result**

✓ Passed

**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front tyres worn unevenly**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** General corrosion to underside of vehicle components**MOT #19**

2023-03-23 10:59

**MOT test number**

845815602160

**Result**

✗ Failed

**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Front tyres worn unevenly**Fail** Offside Rear Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting inner sill panel area (6.2.2 (d) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** General corrosion to underside of vehicle components**Fail** Nearside Rear Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting inner sill panel area (6.2.2 (d) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**MOT #18**

2022-02-21 12:55

**MOT test number**

239735853443

**Result**

✓ Passed

**MOT #17** 2022-02-17 11:34**MOT test number** 858306539870**Result** ✗ Failed

**Fail** Offside Front Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting (6.2.2 (d) (i))

**MOT #16** 2021-03-19 15:54**MOT test number** 748648739316**Result** ✓ Passed**MOT #15** 2020-02-14 15:03**MOT test number** 116774189732**Result** ✓ Passed

**Advice** Offside Front Lower Fog light inop.

**MOT #14** 2020-02-12 11:49**MOT test number** 886983599564**Result** ✗ Failed

**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

**Advice** Offside Front Lower Fog light inop.

**MOT #13** 2019-01-22 15:05**MOT test number** 980641495653**Result** ✓ Passed



MOT #12	2017-10-12 12:20
MOT test number	769094309849
Result	✓ Passed
Advice	Nearside Front Brake pipe slightly corroded leading to hose (3.6.B.2c)
Advice	Exhaust has a minor leak of exhaust gases silencer box (7.1.2)
Advice	Offside Front Brake pipe slightly corroded leading to hose (3.6.B.2c)
Advice	Rear registration plate faded but not likely to be misread (6.3.1d)

MOT #11	2017-07-11 13:07
MOT test number	317939942278
Result	✓ Passed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #10	2016-04-29 15:04
MOT test number	403263694605
Result	✓ Passed
Advice	Engine cover fitted
Advice	Under trays fitted

**MOT #9**

2016-04-29 15:04

**MOT test number**

953932531415

**Result****✗ Failed****Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Engine cover fitted**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Under trays fitted**MOT #8**

2015-02-03 11:58

**MOT test number**

769894135046

**Result****✓ Passed****Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #7**

2014-01-27 14:15

**MOT test number**

158317524051

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Inner Front Brake pipe slightly corroded (3.6.B.2c)**Notice** Sill trims fitted**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Notice** Offside rear tyre wall slightly damaged**Advice** Offside Inner Front Brake pipe slightly corroded (3.6.B.2c)**Notice** Under-trays fitted obscuring some underside components

**MOT #6** 2013-01-16 14:58**MOT test number** 747016013058**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**MOT #5** 2011-12-06 13:14**MOT test number** 935220241305**Result** ✓ Passed**MOT #4** 2010-11-23 10:33**MOT test number** 124447720371**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both front discs are slightly pitted**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2009-09-09 10:50**MOT test number** 911902859248**Result** ✓ Passed**Advice** Rear Brake lining(s) wearing thin (3.5.1g)**MOT #2** 2008-09-11 08:12**MOT test number** 363475858490**Result** ✓ Passed





MOT #1	2008-09-10 18:09
MOT test number	542314758232
Result	✗ Failed
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
4 April 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	4 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-09-12
Last registration	2024-04-05
Complete history	<a href="#">See info</a>



Registration #1	2005-09-12	21 mi
Registration #2	2008-09-10	35.924 mi
Registration #3	2008-09-11	35.924 mi
Registration #4	2009-09-09	38.998 mi
Registration #5	2010-11-23	45.214 mi
Registration #6	2011-12-06	51.011 mi
Registration #7	2013-01-16	53.096 mi
Registration #8	2014-01-27	58.112 mi
Registration #9	2015-02-03	61.337 mi
Registration #10	2016-04-29	65.757 mi
Registration #11	2016-04-29	65.757 mi
Registration #12	2017-07-11	66.200 mi
Registration #13	2018-01-01	66.200 mi
Registration #14	2018-01-01	66.200 mi
Registration #15	2018-01-01	66.200 mi
Registration #16	2018-01-01	66.200 mi
Registration #17	2018-01-01	66.200 mi
Registration #18	2018-01-01	66.200 mi
Registration #19	2018-01-01	66.200 mi
Registration #20	2018-01-01	66.200 mi
Registration #21	2018-01-01	66.200 mi
Registration #22	2018-01-01	66.200 mi
Registration #23	2018-01-01	66.200 mi
Registration #24	2018-01-01	66.200 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	2190 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	1KD1334867