





report date: 2024-03-29

General information

Make	BMW
Model	Z4 Z4 SDRIVE35I M SPORT ROADSTER
Colour	Grey
Year of manufacture	2010
Top speed	155 mph
0 - 60 mph	5.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	302 BHP
Max. torque	400 Nm at 1.300 rpm
Engine capacity	2.979 сс
Cylinders	6
Fuel type	Petrol
Consumption city	20.9 mpg
Consumption extra urban	40.4 mpg
Consumption combined	30.1 mpg
CO2 emission	210 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-08

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

679059791515

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT test number

MOT expiry date	2024-07-25
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	20
Total items failed	5

MOT #14	2023-07-18 09:28
MOT test number	415060444400
Result	✓ Passed
Next expiry date	2024-07-25

MOT #13	2022-07-05 09:40
MOT test number	773144850276
Result	✓ Passed

MOT #12	2021-07-26 10:37
MOT test number	408515172142
Result	✓ Passed

MOT #11	2020-12-04 12:51
MOT test number	524280678370
Result	✓ Passed

MOT #10	2020-12-03 13:15

Result × Failed

Advice Nearside Front Tyre slightly damaged strong advisory deteriorated (5.2.3 (d) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #9 2019-12-19 14:21

MOT test number 442029857119

Result
✓ Passed

MOT #8 2018-11-30 14:29

MOT test number 298469577807

Result ✓ Passed

MOT #7 2017-12-29 16:03

MOT test number 379769130285

Result

Passed

Advice Undertrays fitted not allowing inspection of some components

Advice Engine covers fitted not allowing inspection of some components

MOT #6 2017-12-29 10:11

MOT test number 922563923854

Result X Failed

Advice Undertrays fitted not allowing inspection of some components

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Engine covers fitted not allowing inspection of some components

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #5 2016-12-14 13:51

MOT test number 573580611891

Result J Passed

Advice Shields fitted upper and lower

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #4		2015-12-04 09:31
MOT test	number	690936341995
Result		✓ Passed
MOT #3		2014-12-15 14:15
MOT test	number	609819244300
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Tread low on inner edges of both front tyres	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A	'(8.3.1d)

MOT #2		2013-12-02 10:08
MOT test	number	199196433391
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A'	(8.3.1d)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	

CarCheck.co.uk page 5/13



report date: 2024-03-29

2013-12-02 10:08 **MOT #1 MOT test number** 326316533330 Result **★** Failed **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Pass with rectification Offside Front Headlamp aim too high (1.8) Notice Engine covers fitted obscuring some components in the engine bay Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Under-trays fitted obscuring some underside components Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this BMW had different number plates. nber of plates faste since

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-12-23
Last registration	2023-07-18
Complete history	See info



Registration #1	2010-12-23	16 mi
Registration #2	2013-12-02	15.965 mi
Registration #3	2014-12-15	18.243 mi
Registration #4	2015-12-04	21.264 mi
Registration #5	2016-12-14	25.945 mi
Registration #6	2017-12-29	31.196 mi
Registration #7	2017-12-29	31.196 mi
Registration #8	2018-11-30	36.790 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		D.277 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1284 mm
Length	4244 mm
Wheel base	2496 mm
Kerb weight	1600 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 13,

Number of axles 2

Engine number 11287478