




report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER DCI TEKNA
Colour	Grey
Year of manufacture	2013
Top speed	115 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 3.600 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.1 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L







Internet history

Entry 1

Date	2021-11-03
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-01
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	1

MOT #10	2023-10-25 09:33
MOT test number	150276253478
Result	✓ Passed
Next expiry date	2024-11-01
Advice	Front Prop shaft joint worn, but not excessively prop rear uj (6.1.7 (c) (i))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #9	2022-10-31 08:39
MOT test number	998291157388
Result	✓ Passed

MOT #8	2021-11-02 09:16
MOT test number	376213828219
Result	✓ Passed

MOT #7	2021-10-28 13:45
MOT test number	478045020596
Result	✗ Failed
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #6** 2020-10-14 13:05**MOT test number** 545350027995**Result** ✓ Passed**MOT #5** 2019-10-17 09:32**MOT test number** 711349871214**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #4** 2018-10-30 15:27**MOT test number** 398827040894**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #3** 2017-10-26 15:05**MOT test number** 444984052174**Result** ✓ Passed**MOT #2** 2016-10-24 15:08**MOT test number** 409456456818**Result** ✓ Passed**Advice** Unable to check rear seat belts vehicle is full of equipment



MOT #1	2016-10-19 13:11
MOT test number	444833284600
Result	✗ Failed
Fail	Nearside Side repeater has less than 50% of the light sources illuminating (1.4.A.2c)
Advice	Unable to check rear seat belts vehicle is full of equipment



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	HX63VXR
Plate since	2019-09-29
Current registration	HX63VXR
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-10-31
Last registration	2023-10-25
Complete history	See info



Registration #1	2013-10-31	12 mi
Registration #2	2016-10-19	36.904 mi
Registration #3	2016-10-24	36.904 mi
Registration #4	2017-10-26	53.405 mi
Registration #5	2018-10-30	67.946 mi
Registration #6	2019-10-17	79.080 mi
Registration #7	2020-10-20	91.217 mi
Registration #8	2021-10-20	103.354 mi
Registration #9	2022-10-20	115.491 mi
Registration #10	2023-10-20	127.628 mi
Registration #11	2023-10-20	139.765 mi
Registration #12	2023-10-20	151.902 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1848 mm
Height	1785 mm
Length	4813 mm
Wheel base	2853 mm
Kerb weight	2160 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	43741B