





report date: 2024-03-29

## General information

Make	MERCEDES-BENZ
Model	S-Class S320L CDI
Colour	Silver
Year of manufacture	-
Top speed	144 mph
0 - 60 mph	8.5 seconds
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	197 BHP
Max. torque	470 Nm at 1.800 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	35.3 mpg



CarCheck.co.uk page 1/14



# Internet history

## Entry 2

Date 2021	-07-26
-----------	--------

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-07-25
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT #22	2021-11-06 15:17
MOT test number	311788845980
Result	✓ Passed
Next expiry date	2022-11-08
Advice Front Wheel bearing has slight play offside and nearside (5.1.3 (a) (i))	

MOT #21		2020-11-09 14:46
MOT test number		537007550251
Result		<b>✓</b> Passed
MOT #20		2019-05-09 09:39
MOT test number		454387331664
Result		✓ Passed
MOT #19		2018-01-31 17:53
MOT test number		996960629066
Result		<b>✓</b> Passed
Advice Offside Front Pla	y in steering rack inner joint(s)	
Advice Nearside Rear Ve	ehicle structure has slight corrosion (6.1.B.2	2)
<b>Advice</b> Nearside Front w	heel bearing has slight play (2.5.A.3c)	

CarCheck.co.uk page 3/14



**Advice** 

LW51FHL report date: 2024-03-29

**MOT #18** 2018-01-29 11:14 468950285944 **MOT** test number Result × Failed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Nearside Rear Vehicle structure has slight corrosion (6.1.B.2) Advice Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b) Advice Offside Front Play in steering rack inner joint(s) Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b) Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail

MOT #17	2017-01-30 17:11
MOT test number	130182075999
Result	✓ Passed

Nearside Front wheel bearing has slight play (2.5.A.3c)

MOT #16	2017-01-30 11:23
MOT test number	323609658000
Result	<b>×</b> Failed
Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)	

CarCheck.co.uk page 4/14



**MOT #15** 2016-01-11 12:27

**MOT test number** 518774693310

**Result** ✓ Passed

**Advice** Slight play in both inner rack joints

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Front wheel bearings slight play

**Advice** Tyre worn close to the legal limit all four (4.1.E.1)

**MOT #14** 2015-01-27 12:25

**MOT test number** 565007125087

Result \( \sqrt{Passed} \)

**Notice** Nearside front, lower rear ball joint slight play

**Notice** Offside front, lower rear ball joint slight play

**Notice** Front brake discs scored/worn

MOT #13 2015-01-22 11:43

**MOT test number** 466232325054

Result × Failed

**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

**Notice** Offside front, lower rear ball joint slight play

**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)

**Notice** Front brake discs scored/worn

**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)

**Notice** Nearside front, lower rear ball joint slight play

**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)

CarCheck.co.uk page 5/14



MOT #12

MOT test number

Result

Notice Front brake performance slight judder

Notice Nearside front/rear brake pipes slight corrosion

MOT #11

Result

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Notice Front brake performance slight judder

Notice Nearside front/rear brake pipes slight corrosion

**MOT #10** 2013-01-03 17:36 **MOT** test number 135253703432 Passed Result **Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c) Notice Front tyres wearing on edges Advice Offside Track rod end ball joint has slight play (2.2.B.1f) Notice SRS lamp on **Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c) Notice N/s/r tyre worn/deteriorated to limits **Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c) Notice O/s/r suspension lower joint worn/slight play

CarCheck.co.uk page 6/14



× Failed

**MOT #9** 2013-01-03 17:36

**MOT test number** 305143603003

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**Notice** Front tyres wearing on edges

**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)

Notice SRS lamp on

Result

**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**Notice** N/s/r tyre worn/deteriorated to limits

**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**Notice** O/s/r suspension lower joint worn/slight play

**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #8 2012-01-13 10:47

**MOT test number** 158823512474

Result \( \sqrt{Passed} \)

Notice Oil leak

**Notice** Under-trays fitted obscuring some underside components

Notice Airbag lamp on

**Notice** Engine covers fitted obscuring some components in the engine bay

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2011-01-20 09:28

**MOT test number** 669280121069

**Result** ✓ Passed

CarCheck.co.uk page 7/14



MOT #6 2010-01-11 11:53

**MOT test number** 783021210071

**Result** ✓ Passed

MOT #5 2009-01-30 09:31

**MOT test number** 974440639066

**Result** ✓ Passed

**MOT #4** 2008-01-30 13:30

**MOT test number** 343220038074

Result \( \sqrt{Passed} \)

MOT #3 2008-01-29 13:03

**MOT test number** 671419028082

Result × Failed

**Fail** Fuel system component leaking (7.2.3)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)

**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2007-01-19 10:51

**MOT test number** 624989217060

Result \( \sqrt{Passed} \)

**MOT #1** 2006-01-27 08:13

**MOT test number** 382007826031

**Result** ✓ Passed

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MERCEDES-BENZ salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



## Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How man MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Export here.	
*******	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NE SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



## Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

**Contact info** 


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2002-01-18
Last registration	2021-11-06
Complete history	See info



Registration #1	2002-01-18	27 mi
Registration #2	2006-01-27	63.385 mi
Registration #3	2007-01-19	75.006 mi
Registration #4	2008-01-29	84.069 mi
Registration #5	2008-01-30	84.069 mi
Registration #6	2009-01-30	91.372 mi
Registration #7	2010-01-11	100.815 mi
Registration #8	2011-01-20	108.640 mi
Registration #9	2012-01-13	114.465 mi
Registration #10	2013-01-03	121.632 mi
Registration #11		0.77 es
Registration #12		11.777 es
Registration #13		0.77 es
Registration #14		11.777 es
Registration #15		0.77 es
Registration #16		11.777 es
Registration #17		0.77 es
Registration #18		11.777 66
Registration #19		0.0746
Registration #20		11.777 es

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2092 mm
Height	1444 mm
Length	5038 mm
Wheel base	2965 mm
Kerb weight	1830 kg

## Additional information

Fuel tank capacity	88 I
Fuel delivery	Direct Injection
Number of doors	4
Engine number	61396030085137

CarCheck.co.uk page 14/14