



**FGIOJPY**

report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC 110
Colour	Silver
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-05
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #13</b>	2023-02-06 11:56
<b>MOT test number</b>	478732361784
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-02-07
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Front Tyre slightly damaged/cracking or perishing both front tyres are worn (5.2.3 (d) (ii))
<b>Advice</b>	Rear Tyre worn close to legal limit/worn on edge both rear tyres (5.2.3 (e))

<b>MOT #12</b>	2022-02-08 11:19
<b>MOT test number</b>	766731591229
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2021-06-01 09:43
<b>MOT test number</b>	167146395855
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2020-06-08 08:46
<b>MOT test number</b>	782067123880
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2019-06-08 10:03
<b>MOT test number</b>	870779161899
<b>Result</b>	✓ Passed

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #8</b>	2018-05-30 09:48
<b>MOT test number</b>	843385560969
<b>Result</b>	✓ Passed

**MOT #7** 2017-06-02 09:02**MOT test number** 136454184655**Result** ✓ Passed**MOT #6** 2016-06-13 14:36**MOT test number** 632793486444**Result** ✓ Passed**MOT #5** 2015-06-26 16:14**MOT test number** 457437475189**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** O/s/r tyre cut in wall**MOT #4** 2015-06-26 11:44**MOT test number** 725217675196**Result** ✗ Failed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** O/s/r tyre cut in wall**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2014-06-27 16:39**MOT test number** 176088974169**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2014-04-26 11:30
MOT test number	808126814158
Result	✓ Passed

MOT #1	2013-05-18 12:32
MOT test number	599578733129
Result	✓ Passed

**Notice** Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-05-22
Last registration	2023-02-06
Complete history	<a href="#">See info</a>



Registration #1	2010-05-22	14 mi
Registration #2	2013-05-18	39.604 mi
Registration #3	2014-04-26	46.230 mi
Registration #4	2014-06-27	47.824 mi
Registration #5	2015-06-26	58.327 mi
Registration #6	2015-06-26	58.327 mi
Registration #7	2016-06-13	65.876 mi
Registration #8	2017-06-02	71.748 mi
Registration #9	2018-06-02	78.600 mi
Registration #10	2019-06-02	85.452 mi
Registration #11	2020-06-02	92.304 mi
Registration #12	2021-06-02	99.156 mi
Registration #13	2022-06-02	106.008 mi
Registration #14	2023-02-06	112.860 mi
Registration #15	2023-02-06	112.860 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9K40003