



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 LOOK
Colour	Silver
Year of manufacture	-
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-07
Pictures	11
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #17</b>	2022-11-17 16:33
<b>MOT test number</b>	380000695595
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-11-17
<b>Advice</b>	Central Front Oil leak, but not excessive engine oil area (8.4.1 (a) (i))

<b>MOT #16</b>	2022-11-15 16:36
<b>MOT test number</b>	458622170401
<b>Result</b>	✗ Failed
<b>Advice</b>	Central Front Oil leak, but not excessive engine oil area (8.4.1 (a) (i))
<b>Fail</b>	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
<b>Advice</b>	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
<b>Fail</b>	Nearside Front Outer Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
<b>Fail</b>	Emissions not tested test aborted CO & lambda (8.2.1.2 (d))

<b>MOT #15</b>	2021-11-18 16:55
<b>MOT test number</b>	861536415322
<b>Result</b>	✓ Passed

<b>MOT #14</b>	2021-01-07 12:57
<b>MOT test number</b>	964139456304
<b>Result</b>	✓ Passed
<b>Advice</b>	O/s/r wheel bearing slightly noisy

<b>MOT #13</b>	2020-01-03 12:41
<b>MOT test number</b>	129311077465
<b>Result</b>	✓ Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2020-01-03 11:37**MOT test number** 720753158116**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #11** 2019-01-11 12:25**MOT test number** 467141401051**Result** ✓ Passed**MOT #10** 2018-03-18 12:17**MOT test number** 977728547468**Result** ✓ Passed**MOT #9** 2018-03-18 12:17**MOT test number** 879068378776**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #8** 2017-03-10 15:09**MOT test number** 200996843319**Result** ✓ Passed**MOT #7** 2016-03-08 10:56**MOT test number** 539928655103**Result** ✓ Passed

**MOT #6** 2016-03-08 10:56**MOT test number** 216863768300**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #5** 2015-02-18 11:37**MOT test number** 916439945095**Result** ✓ Passed**Notice** Rear silencer corroded**Notice** Rear wiper split**Notice** Play in steering rack inner joint(s)**MOT #4** 2014-03-10 11:25**MOT test number** 198019564412**Result** ✓ Passed**MOT #3** 2013-02-11 14:44**MOT test number** 285962043027**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #2** 2012-02-04 11:09**MOT test number** 559585132069**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Play in steering rack inner joint(s)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nail in offside rear tyre



MOT #1	2011-02-11 10:59
MOT test number	567752441023
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>GU08BZR</b>
Plate since	2019-09-28
Current registration	<b>GU08BZR</b>
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-01
Last registration	2022-11-17
Complete history	<a href="#">See info</a>



Registration #1	2008-03-01	24 mi
Registration #2	2011-02-11	23.361 mi
Registration #3	2012-02-04	31.958 mi
Registration #4	2013-02-11	41.468 mi
Registration #5	2014-03-10	52.141 mi
Registration #6	2015-02-18	56.002 mi
Registration #7	2016-03-08	60.459 mi
Registration #8	2016-03-08	60.459 mi
Registration #9	2017-03-10	63.077 mi
Registration #10	2018-03-18	69.791 mi
Registration #11	2019-03-20	75.277 mi
Registration #12	2019-03-20	75.277 mi
Registration #13	2019-03-20	75.277 mi
Registration #14	2019-03-20	75.277 mi
Registration #15	2019-03-20	75.277 mi
Registration #16	2019-03-20	75.277 mi
Registration #17	2019-03-20	75.277 mi
Registration #18	2019-03-20	75.277 mi
Registration #19	2019-03-20	75.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FST65804163