





report date: 2024-03-28

### General information

| Make                | HONDA                |
|---------------------|----------------------|
| Model               | CIVIC I-DTEC SE PLUS |
| Colour              | Grey                 |
| Year of manufacture | 2014                 |
| Top speed           | 129 mph              |
| 0 - 60 mph          | 10.5 seconds         |
| Gearbox             | 6 speed Manual       |

### Engine & fuel consumption

| Power                   | 118 BHP             |
|-------------------------|---------------------|
| Max. torque             | 300 Nm at 2.000 rpm |
| Engine capacity         | 1.597 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 70.6 mpg            |
| Consumption extra urban | 85.6 mpg            |
| Consumption combined    | 78.5 mpg            |
| CO2 emission            | 94 g/km             |
| CO2 label               | Α                   |



CarCheck.co.uk page 1/10



MOT history

| MOT expiry date    | 2024-12-21 |
|--------------------|------------|
| MOT pass rate      | 80 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 1          |
| Total advice items | 4          |
| Total items failed | 4          |

| MOT #5  |  | 2023-12-12 11:14 |
|---|--|------------------|
| MOT test  | number   | 882269694644     |
| Result  |  | ✓ Passed         |
| Next expiry date 2024-12-   |  | 2024-12-21       |
| Advice Registration plate deteriorated but not likely to be misread (0.1 (b)) |  |                  |
| Advice  | Tyre worn close to legal limit/worn on edge all 4 either 2/3mm or low on e | edge (5.2.3 (e)) |

| MOT #4  | 2022-12-22 11:59 |
|---|------------------|
| MOT test number   | 369963891961     |
| Result  | <b>✓</b> Passed  |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| MOT #3   | 2022-12-17 11:40 |
|--|------------------|
| MOT test number  | 652152272237     |
| Result   | <b>×</b> Failed  |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))   |                  |
| Fail Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)) |                  |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))  |                  |
| Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))   |                  |

CarCheck.co.uk page 2/10



report date: 2024-03-28

| MOT #2          | 2021-12-07 17:16 |
|-----------------|------------------|
| MOT test number | 387182787397     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #1          | 2021-04-24 17:46 |
| MOT test number | 572124818394     |
|                 |                  |

CarCheck.co.uk page 3/10



Tax & MOT check



| Tax status       | Valid until 1 March |
|------------------|---------------------|
| Days left        | 307                 |
| MOT expiry date  | 21 December 2024    |
| Full MOT history | See MOT history     |

### Tax calculation

| Vehicle class                           | 49             |
|---|----------------|
| Band                                    | A              |
| Single payment (12 months)              | £ 0,00,-       |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 4/10



report date: 2024-03-28

### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Type     |  |



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this HONDA had different number plates. about of pliates faste since

CarCheck.co.uk page 7/10



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 6          |
| First mileage registration | 2014-09-22 |
| Last registration          | 2023-12-12 |
| Complete history           | See info   |



| Registration #1 | 2014-09-22 | 8 mi      |
|-----------------|------------|-----------|
| Registration #2 | 2021-04-24 | 76.602 mi |
| Registration #3 | 2021-12-07 | 82.173 mi |
| Registration #4 |            | 11.777 es |
| Registration #5 |            | 11.777 es |
| Registration #6 |            | 0.77      |

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 94%             |
| Children       | 83%             |
| Pedestrian     | 69%             |
| Safety systems | 86%             |
| Overall rating | 86%             |
| Video          | see crash video |



## Dimensions & weight

| Width               | 2065 mm |
|---------------------|---------|
| Height              | 1470 mm |
| Length              | 4300 mm |
| Kerb weight         | 1428 kg |
| Max. allowed weight | 1870 kg |

## Additional information

| Fuel tank capacity | 50 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | N16A12001722     |

CarCheck.co.uk page 10/10