



report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Blue
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-17
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	33
Total items failed	7

MOT #15 2024-01-06 09:06

MOT test number 532147557346

Result ✓ Passed

Next expiry date 2025-01-17

- Advice** Rear Exhaust mounting defective tail pipe (6.1.2 (a))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))
- Advice** Rear Suspension arm corroded but not seriously weakened all arms (5.3.3 (b) (i))
- Advice** Front Direction indicator slightly discoloured both (4.4.3 (a))
- Advice** Oil leak, but not excessive gear box (8.4.1 (a) (i))
- Advice** Sill protectors fitted

MOT #14 2023-01-05 14:46

MOT test number 970934694188

Result ✓ Passed

MOT #13 2022-01-18 10:46

MOT test number 286839543536

Result ✓ Passed

**MOT #12** 2021-05-31 13:57**MOT test number** 770947377377**Result** ✓ Passed**MOT #11** 2021-05-31 11:48**MOT test number** 450522748944**Result** ✗ Failed**Fail** Rear Anti-roll bar linkage fractured both sides (5.3.3 (b) (ii))**MOT #10** 2019-07-02 07:48**MOT test number** 115481721451**Result** ✓ Passed**MOT #9** 2019-06-28 10:21**MOT test number** 492303405891**Result** ✗ Failed**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #8** 2018-06-27 07:45**MOT test number** 240596840925**Result** ✓ Passed**Advice** Coil spring corroded both front and nearside rear (5.3.1 (b) (i))**Advice** Exhaust system corroded

**MOT #7**

2018-06-22 08:54

MOT test number

444174403153

Result**✗ Failed**

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Coil spring corroded both front and nearside rear (5.3.1 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))
- Advice** Centre and rear exhaust heat shields insecure
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))
- Advice** Exhaust system corroded

MOT #6

2017-06-24 08:02

MOT test number

478739228747

Result**✓ Passed**

- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)
- Advice** Rear hanger for exhaust corroded and detached, exhaust still adequately supported.
- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)

**MOT #5** 2017-06-24 08:02**MOT test number** 841317752411**Result** ✗ Failed

- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Rear bush (2.4.G.2)
- Pass with rectification** Nearside Steering rack gaiter insecure (2.2.D.2d)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Rear hanger for exhaust corroded and detached, exhaust still adequately supported.
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Rear bush (2.4.G.2)

MOT #4 2016-06-21 08:48**MOT test number** 220919658253**Result** ✓ Passed**MOT #3** 2015-06-18 13:46**MOT test number** 556839565134**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2014-06-25 12:24**MOT test number** 339426874110**Result** ✓ Passed



MOT #1	2013-06-28 09:24
MOT test number	489599773128
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
17 January 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-08-03
Last registration	2024-01-06
Complete history	See info



Registration #1	2010-08-03	20 mi
Registration #2	2013-06-28	23.086 mi
Registration #3	2014-06-25	33.824 mi
Registration #4	2015-06-18	44.451 mi
Registration #5	2016-06-21	53.058 mi
Registration #6	2017-06-24	63.052 mi
Registration #7	2017-06-24	63.052 mi
Registration #8	2018-06-22	74.886 mi
Registration #9	2018-06-27	74.889 mi
Registration #10	2019-06-20	0 mi
Registration #11	2020-06-20	0 mi
Registration #12	2021-06-20	0 mi
Registration #13	2022-06-20	0 mi
Registration #14	2023-06-20	0 mi
Registration #15	2024-01-06	0 mi
Registration #16	2024-03-28	0 mi
Registration #17	2024-03-28	0 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AL38072