





### General information

Make	VOLVO
Model	V60 D3 ES
Colour	Gold
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С








## Internet history

Entry 2	
Date	2021-07-24
Pictures	39
Listing price	View report



#### source: yesauto.com

Entry 1	
Date	2021-07-19
Pictures	1
Listing price	View report



source: autotrader.co.uk





# MOT history

MOT expiry date	2024-08-08
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	8
Total items failed	1

МОТ #9	2023-08-02 08:41
MOT test number	231388979237
Result	✓ Passed
Next expiry date	2024-08-08

MOT #8		2022-08-04 12:45
MOT test	number	828826357937
Result		✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge worn (5.2.3 (e))	
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge bald (5.2.3 (e))	

MOT #7	2021-08-09 14:57
MOT test number	937471085701
Result	✓ Passed

MOT #6	2020-10-15 11:04
MOT test	<b>number</b> 707755775813
Result	✓ Passed
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))





MOT #5	2020-10-15 09:30
MOT test number	958448081757
Result	🗙 Failed
Advice Offside Front Suspension arm pin or bush worn but not resulting in ex (i))	cessive movement (5.3.4 (a)
Advice Front Inner Brake disc worn, pitted or scored, but not seriously weake	ned (1.1.14 (a) (ii))
<b>Fail</b> Offside Track rod end ball joint dust cover excessively damaged or determined prevents the ingress of dirt (2.1.3 (g) (ii))	orated so that it no longer
МОТ #4	2019-10-15 11:23
MOT test number	188682621071
Result	✓ Passed
MOT #3	2018-10-16 11:32
MOT test number	440698031946
Result	✓ Passed
MOT #2	2017-10-14 10:18
MOT test number	485863323040
Result	✓ Passed
	•
MOT #1	2016-09-24 08:08
MOT test number	688282804532
Result	✓ Passed
Advice Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

<b>Tax due:</b> 1 August 2024	✓ Taxed	<b>Expires:</b> 8 August 2024	✓ мот
Tax status			Valid until 1 August
Days left			94
MOT expiry date			8 August 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	 
Category	 AMPL
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	
**********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-10-22
Last registration	2023-08-02
Complete history	<u>See info</u>



Registration #1	2013-10-22	6 mi
Registration #2	2016-09-24	30.255 mi
Registration #3	2017-10-14	42.323 mi
Registration #4	2018-10-16	49.496 mi
Registration #5	2019-10-15	51.539 mi
Registration #6	2020-10-15	52.129 mi
Registration #7		11.777 esi
Registration #8		10.200 est
Registration #9		11.777 mi
Registration #10		11.117 esi
Registration #11		11.777 esi
Registration #12		11.117 est

More info >





### Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
50566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	<u>see crash video</u>



Dimensions & weight	
Width	2097 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1632 kg
Max. allowed weight	2180 kg
Additional information	
Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11