





report date: 2024-03-29

General information

Make	BMW	
Model	318 118I M SPORT SHADOW EDITION	
Colour	Silver	
Year of manufacture	2018	
Top speed	130 mph	
0 - 60 mph	8.5 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 4.300 rpm
Engine capacity	1.499 сс
Cylinders	3
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	137 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-07-20

Pictures 35

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2025-04-08
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	12
Total items failed	6

MOT #7	2024-04-09 13:43	
MOT test number	849005013950	
Result	✓ Passed	
Next expiry date	2025-04-08	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 225/45/18rf (5.2.3 (e)) Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front breaker arm bush (5.3.4 (a) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front breaker arm bush (5.3.4 (a) (i))		

MOT #6		2024-04-06 10:23
MOT test n	umber	425726949134
Result		× Failed
Fail From	ont Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front breaker arm bush (5.3.4 (a) (i))		
Advice	Advice Nearside Front Tyre worn close to legal limit/worn on edge 225/45/18rf (5.2.3 (e))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front breaker arm bush (5.3.4 (a) (i))		

CarCheck.co.uk page 3/11



MOT #5 2023-02-22 11:19

MOT test number 643409498072

MOT #4 2022-02-21 12:48

MOT test number 882463748305

Advice Offside Rear Tyre worn close to legal limit/worn on edge OSR TYRE 1-2-1 MM TREAD, ADVISE ONLY JUST MET MOT STANDARD, REPLACE A.S.A.P. (255-40X18Y) (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge NSR TYRE 2-1.6 MM ,ADVISE ONLY JUST MET MOT STANDARD,REPLACE A.S.A.P. (5.2.3 (e))

MOT #3 2022-02-09 14:25

MOT test number 659932347978

Result X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge OSR TYRE 1-2-1 MM TREAD, ADVISE ONLY JUST MET MOT STANDARD, REPLACE A.S.A.P. (255-40X18Y) (5.2.3 (e))

Fail Front Registration plate does not conform to the specified requirements (0.1 (d))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge NSR TYRE 2-1.6 MM ,ADVISE ONLY JUST MET MOT STANDARD,REPLACE A.S.A.P. (5.2.3 (e))

Fail Rear Registration plate does not conform to the specified requirements (0.1 (d))

MOT #2 2021-02-16 15:23

MOT test number 526155316325

Result \(\sqrt{Passed} \)

MOT #1 2021-02-16 15:23

MOT test number 810470836799

Result X Failed

Pass with rectification Front Registration plate incorrect (0.1 (c))

Pass with rectification Rear Registration plate incorrect (0.1 (c))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



o which initially	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report is	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-02-21
Last registration	2024-04-09
Complete history	See info



Registration #1	2018-02-21	26 mi
Registration #2	2021-02-16	31.087 mi
Registration #3	2021-02-16	31.087 mi
Registration #4	2022-02-09	42.336 mi
Registration #5	2022-02-21	42.460 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
50295	
50482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1984 mm
Height	1440 mm
Length	4329 mm
Wheel base	2690 mm
Kerb weight	1305 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	52 l	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ige 11/11