





report date: 2024-03-28

## General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI BLUEEFFICIENCY SPORT
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	11.9 seconds
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	80 kW / 109 HP / 107 BHP
Max. torque	260 Nm at 2.500 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



# Internet history

# Entry 2

Date 2023-03-31

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-08-30

Pictures 43

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



**LL64WSY** 

report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-05-12
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #9	2023-05-13 08:56
MOT test number	321186876316
Result	<b>✓</b> Passed
Next expiry date	2024-05-12

MOT #8	2022-09-26 15:50
MOT test number	462879202538
Result	✓ Passed

MOT #7		2022-09-26 11:39
MOT test number	er	180760377137
Result		<b>×</b> Failed
DANGEROUS	Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
DANGEROUS	Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #6	2021-09-28 14:14
MOT test number	289648804388
Result	<b>✓</b> Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



Result

**Advice** 

LL64WSY report date: 2024-03-28

Passed

MOT #5 2020-12-11 11:18

**MOT test number** 581771754485

Result Passed

**Advice** Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2019-11-07 10:01

**MOT test number** 782391945574

Advice Nearside side repeater lens slightly damaged no effect on emitted light

Near side repeater felts slightly durinaged no effect on enficted light

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2018-11-08 16:13

**MOT test number** 302185712285

Result \rightarrow Passed

MOT #2 2017-11-30 12:30

MOT test number 817472655980

Result 

Passed

**MOT #1** 2017-11-30 11:40

**MOT test number** 681709068717

Result × Failed

**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	12 May 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



## Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1

Date

Category

**Type** 

Damage 2

**Date** 

Category

**Type** 



#### **Extra MERCEDES-BENZ salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



## Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



**LL64WSY** 

report date: 2024-03-28

Owner	history
O WILCI	,

·	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. E report here.	
********	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
********	
***************************************	
*************	
Plate changes	More info >
See in this check if this MERCEDES-BENZ had different number plates.	
Mumber of plates	,
Current registration	OK SIE
Plate since	
Current registration	NIK NIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



## Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-12-22
Last registration	2023-05-13
Complete history	See info



Registration #1	2014-12-22	17 mi
Registration #2	2017-11-30	39.417 mi
Registration #3	2017-11-30	24.498 mi
Registration #4	2018-11-08	33.018 mi
Registration #5	2019-11-07	36.936 mi
Registration #6	2020-12-11	39.685 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		N.777-au

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	97%
Children	81%
Pedestrian	56%
Safety systems	86%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	2010 mm
Height	1557 mm
Length	4359 mm
Wheel base	2699 mm
Kerb weight	1475 kg
Max. allowed weight	2000 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	page 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	K9KF451D038160