



report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Red
Year of manufacture	2012
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-09-11
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-08-10
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	22
Total items failed	3

MOT #11 2023-08-01 14:44

MOT test number 701184281956

Result ✓ Passed

Next expiry date 2024-08-10

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracks in tread (5.2.3 (d) (ii))
- Advice** Underside of body corroding
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing Cracks in tread (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracks in tread (5.2.3 (d) (ii))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #10 2022-08-04 14:10

MOT test number 951349766325

Result ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Brake pipe corroded, covered in grease or other material Slight corrosion offside rear and nearside front (visible in wheel arch.) Heavier corrosion offside front (visible in wheel arch). (1.1.11 (c))

**MOT #9**

2021-08-04 09:33

**MOT test number**

516884844651

**Result**

✓ Passed

- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #8**

2020-08-11 11:31

**MOT test number**

322760595489

**Result**

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #7**

2019-07-24 12:26

**MOT test number**

814445180003

**Result**

✓ Passed

**MOT #6** 2019-07-24 12:26**MOT test number** 198673761961**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #5** 2018-07-25 10:52**MOT test number** 406926981522**Result** ✓ Passed**MOT #4** 2017-07-31 11:28**MOT test number** 571300647951**Result** ✓ Passed**MOT #3** 2016-08-03 09:28**MOT test number** 907134624967**Result** ✓ Passed**MOT #2** 2016-08-03 09:28**MOT test number** 194594610090**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2015-07-23 09:22**MOT test number** 557964405225**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
10 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	10 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-07-31
Last registration	2023-08-01
Complete history	<a href="#">See info</a>



Registration #1	2012-07-31	10 mi
Registration #2	2015-07-23	5.337 mi
Registration #3	2016-08-03	5.680 mi
Registration #4	2016-08-03	5.680 mi
Registration #5	2017-07-31	7.020 mi
Registration #6	2018-07-25	9.882 mi
Registration #7	2019-07-24	13.297 mi
Registration #8	2020-05-20	15.277 mi
Registration #9	2020-05-20	15.277 mi
Registration #10	2020-05-20	15.277 mi
Registration #11	2020-05-20	15.277 mi
Registration #12	2020-05-20	15.277 mi
Registration #13	2023-08-01	15.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	155933