



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Black
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	169 Nm at 2.400 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.5 mpg
CO2 emission	209 g/km
CO2 label	K






Internet history

Entry 2

Date	2021-07-19
Pictures	7
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-18
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-08
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	33
Total items failed	9

MOT #20	2023-08-01 15:51
MOT test number	891179786693
Result	✓ Passed
Next expiry date	2024-08-08

MOT #19	2023-08-01 07:54
MOT test number	343746602360
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Side repeater missing (4.4.1 (a) (ii))
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #18**

2022-08-08 14:12

MOT test number

973257306392

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** EPC light on dash
- Advice** Front Exhaust has a minor leak of exhaust gases Manifold/downpipe area (6.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Outer sidewall cracked (5.2.3 (d) (ii))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #17

2022-08-08 10:50

MOT test number

585710637338

Result

✗ Failed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Advice** EPC light on dash
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Outer sidewall cracked (5.2.3 (d) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases Manifold/downpipe area (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2021-07-29 12:03

MOT test number

110044748274

Result

✓ Passed

**MOT #15** 2021-07-29 09:59**MOT test number** 988076885878**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #14** 2020-08-08 07:14**MOT test number** 439900621138**Result** ✓ Passed**MOT #13** 2019-08-09 14:10**MOT test number** 678984067519**Result** ✓ Passed**MOT #12** 2018-10-19 08:21**MOT test number** 937280909184**Result** ✓ Passed**MOT #11** 2017-10-11 11:10**MOT test number** 222686412658**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2016-10-14 10:46**MOT test number** 503728167667**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 205/55-16 (4.1.E.1)**Advice** Nearside front tyre perishing

**MOT #9** 2016-10-14 08:47**MOT test number** 586819978342**Result** ✗ Failed**Advice** Nearside front tyre perishing**Fail** Offside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure 205/55-16 (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit 205/55-16 (4.1.E.1)**MOT #8** 2015-10-14 07:49**MOT test number** 851130226901**Result** ✓ Passed**Advice** Offside rear tyre perished and split**Advice** Slight movement in steering rack**MOT #7** 2014-10-07 12:19**MOT test number** 268450684249**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #6** 2013-10-16 11:09**MOT test number** 518409583267**Result** ✓ Passed

**MOT #5** 2011-10-10 14:29**MOT test number** 586483581217**Result** ✓ Passed

- Notice** Slight play in n/s steering arm
- Notice** O/s outer sill damaged
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)
- Notice** Oil cap housing damaged and insecure

MOT #4 2010-09-25 10:04**MOT test number** 870978460225**Result** ✓ Passed**MOT #3** 2009-09-29 11:19**MOT test number** 360142479228**Result** ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2008-09-16 11:54**MOT test number** 860920268210**Result** ✓ Passed

- Notice** Advise(slight wear on front discs & pads)
- Notice** Advise(exhaust system beginning to corrode)



MOT #1	2008-09-16 11:54
MOT test number	304170368262
Result	✗ Failed
<div><div>Notice</div> Advise(slight wear on front discs & pads)</div>	
<div><div>Pass with rectification</div> Front Windscreen washer provides insufficient washer liquid (8.2.3)</div>	
<div><div>Notice</div> Advise(exhaust system beginning to corrode)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
8 August 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	SM55KVG
Plate since	2019-03-29
Current registration	SM55KVG
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-10-05
Last registration	2023-08-01
Complete history	See info



Registration #1	2005-10-05	27 mi
Registration #2	2008-09-16	22.509 mi
Registration #3	2009-09-29	32.672 mi
Registration #4	2010-09-25	45.612 mi
Registration #5	2011-10-10	59.107 mi
Registration #6	2013-10-16	73.493 mi
Registration #7	2014-10-07	73.495 mi
Registration #8	2015-10-14	77.103 mi
Registration #9	2016-10-14	78.838 mi
Registration #10	2016-10-14	78.838 mi
Registration #11	2017-10-11	80.536 mi
Registration #12	2018-10-11	82.272 mi
Registration #13	2019-10-11	84.008 mi
Registration #14	2020-10-11	85.744 mi
Registration #15	2021-10-11	87.480 mi
Registration #16	2022-10-11	89.216 mi
Registration #17	2023-08-01	90.952 mi
Registration #18	2023-08-01	90.952 mi
Registration #19	2023-08-01	90.952 mi
Registration #20	2023-08-01	90.952 mi
Registration #21	2023-08-01	90.952 mi
Registration #22	2023-08-01	90.952 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1836 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1309 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	AZJ 736618