



General information

Make	MINI
Model	ONE COOPER HIGHGATE
Colour	Silver
Year of manufacture	2014
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history


Entry 2

Date	2021-10-21
Pictures	0
Listing price	<a href="#">View report</a>

source: heycar.co.uk

Entry 1

Date	2021-06-17
Pictures	45
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-21
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	16
Total items failed	8

MOT #12	2023-08-22 07:45
MOT test number	218127438169
Result	✓ Passed
Next expiry date	2024-08-21

MOT #11	2023-08-17 18:32
MOT test number	839394016193
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #10	2022-10-12 14:16
MOT test number	652479536823
Result	✓ Passed
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #9** 2021-11-04 07:28**MOT test number** 729633998699**Result** ✓ Passed**MOT #8** 2021-06-17 15:45**MOT test number** 127636914519**Result** ✓ Passed**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #7** 2021-04-16 14:45**MOT test number** 180704588005**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both front tyres worn on edges (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged been run soft (5.2.3 (d) (ii))**MOT #6** 2020-04-22 11:10**MOT test number** 852113529547**Result** ✓ Passed

**MOT #5**

2020-04-21 09:53

**MOT test number**

232677816567

**Result****✗ Failed**

- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH REAR (1.1.14 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases FLEX PIPE (6.1.2 (a))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**MOT #4**

2019-09-24 09:11

**MOT test number**

863022562444

**Result****✓ Passed**

- Advice** Offside Front side repeater slightly insecure
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Coolant level low

**MOT #3**

2018-09-17 11:44

**MOT test number**

321474004423

**Result****✓ Passed**

- Advice** Coolant level low
- Advice** Nearside Rear Nail in tyre



MOT #2	2017-09-20 08:17
MOT test number	964902656104
Result	✓ Passed

MOT #1	2017-01-14 13:39
MOT test number	954428504971
Result	✓ Passed
Advice	Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
Advice	N/s/f tyre worn on edges



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
21 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	21 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-01-29
Last registration	2023-08-22
Complete history	<a href="#">See info</a>



Registration #1	2014-01-29	28 mi
Registration #2	2017-01-14	16.607 mi
Registration #3	2017-09-20	19.335 mi
Registration #4	2018-09-17	26.620 mi
Registration #5	2019-09-24	32.329 mi
Registration #6	2020-04-21	35.625 mi
Registration #7	2020-04-22	35.625 mi
Registration #8	2021-04-16	37.546 mi
Registration #9	2022-05-22	38.277 mi
Registration #10	2022-05-22	38.277 mi
Registration #11	2022-05-22	38.277 mi
Registration #12	2022-05-22	38.277 mi
Registration #13	2022-05-22	38.277 mi
Registration #14	2022-05-22	38.277 mi
Registration #15	2022-05-22	38.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1165 kg
Max. allowed weight	1595 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	A309J692