



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA 16V SX
Colour	Silver
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-24
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-18
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	36
Total items failed	7

MOT #20	2023-10-03 10:12
MOT test number	378050602443
Result	✓ Passed
Next expiry date	2024-10-18
Advice	Both headlights only just give a beam image

MOT #19	2022-10-19 15:33
MOT test number	149412889680
Result	✓ Passed
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #18	2022-10-19 15:33
MOT test number	895330112596
Result	✗ Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #17** 2021-09-02 09:31**MOT test number** 670263782492**Result** ✓ Passed**MOT #16** 2021-03-30 13:43**MOT test number** 481972938265**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #15** 2021-03-30 12:53**MOT test number** 270979965969**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #14** 2020-03-17 14:32**MOT test number** 169940447314**Result** ✓ Passed**Advice** Wheel trims fitted not allowing full inspection**MOT #13** 2020-03-17 10:39**MOT test number** 451977834066**Result** ✗ Failed**Advice** Wheel trims fitted not allowing full inspection**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #12**

2019-03-18 11:38

MOT test number

786593353997

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11

2019-03-18 09:50

MOT test number

711412637053

Result

✗ Failed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10

2018-03-28 11:34

MOT test number

818446138904

Result

✓ Passed

- Advice** Nearside Front tyre perished
- Advice** Offside Rear tyre perished
- Advice** Spare tyre defective
- Advice** Nearside Rear tyre perished

**MOT #9** 2017-03-20 15:24**MOT test number** 774623283165**Result** ✓ Passed**Advice** Nearside rear tyre cracked and perished**MOT #8** 2016-03-22 13:59**MOT test number** 873366263567**Result** ✓ Passed**Advice** Nearside and offside rear tyres heavily cracked and perished**Advice** Nearside front tyre cracked and perished**MOT #7** 2015-03-25 13:59**MOT test number** 985274085071**Result** ✓ Passed**Notice** Nearside and Offside rear tyres heavily cracked and perished**Notice** Nearside front tyre cracked and perished**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2014-03-26 12:26**MOT test number** 805555084033**Result** ✓ Passed**Notice** Offside front tyre cracked and perished**Notice** Nail in offside rear tyre**Notice** Nearside and Offside rear tyres cracked and perished

**MOT #5** 2013-03-21 11:03**MOT test number** 317970283019**Result** ✓ Passed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** All four tyres sidewalls slightly perished**MOT #4** 2013-03-21 11:03**MOT test number** 197960683425**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** All four tyres sidewalls slightly perished**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #3** 2012-03-19 11:35**MOT test number** 675559572050**Result** ✓ Passed**MOT #2** 2011-03-19 11:39**MOT test number** 387348571013**Result** ✓ Passed**MOT #1** 2010-03-26 14:19**MOT test number** 194945480424**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
18 October 2024

Tax status		Valid until 1 September
Days left		125
MOT expiry date		18 October 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 HW07EXU
Plate since	2019-03-29
Current registration	 HW07EXU
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-30
Last registration	2023-10-03
Complete history	See info



Registration #1	2007-03-30	8 mi
Registration #2	2010-03-26	8.458 mi
Registration #3	2011-03-19	10.735 mi
Registration #4	2012-03-19	12.991 mi
Registration #5	2013-03-21	15.365 mi
Registration #6	2014-03-26	18.110 mi
Registration #7	2015-03-25	21.107 mi
Registration #8	2016-03-22	23.283 mi
Registration #9	2017-03-20	23.729 mi
Registration #10	2018-03-28	26.034 mi
Registration #11	2019-03-18	28.664 mi
Registration #12	2020-03-20	31.377 mi
Registration #13	2021-03-20	34.177 mi
Registration #14	2022-03-20	37.177 mi
Registration #15	2023-03-20	40.377 mi
Registration #16	2024-03-20	43.777 mi
Registration #17	2025-03-20	47.377 mi
Registration #18	2026-03-20	51.177 mi
Registration #19	2027-03-20	55.177 mi
Registration #20	2028-03-20	59.377 mi
Registration #21	2029-03-20	63.777 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1667 mm
Height	1521 mm
Length	3850 mm
Wheel base	2460 mm
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6F3239543