




General information

| | |
|---------------------|----------------|
| Make | FORD |
| Model | FOCUS ZETEC |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 123 mph |
| 0 - 60 mph | 10.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 123 BHP |
| Max. torque | 165 Nm at 4.000 rpm |
| Engine capacity | 1.798 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 29.1 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 39.8 mpg |
| CO2 emission | 167 g/km |
| CO2 label | H |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-15 |
| Pictures | 1 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-20 |
| MOT pass rate | 86 % |
| MOT passed | 12 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 2 |

| | |
|------------------|------------------|
| MOT #14 | 2023-05-30 10:20 |
| MOT test number | 731006106675 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-20 |

| | |
|-----------------|--|
| MOT #13 | 2022-05-23 14:28 |
| MOT test number | 526158416901 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|-----------------|------------------|
| MOT #12 | 2021-06-21 09:27 |
| MOT test number | 779935963826 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #11 | 2021-06-18 11:19 |
| MOT test number | 664004219134 |
| Result | ✗ Failed |
| Advice | Offside Rear Direction indicator slightly discoloured (4.4.3 (a)) |
| Advice | Offside Rear Nail in tyre |
| Fail | Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |

**MOT #10** 2020-11-30 16:25**MOT test number** 179324085535**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2019-11-27 10:08**MOT test number** 120368446699**Result** ✓ Passed**MOT #8** 2018-11-02 15:42**MOT test number** 906577561084**Result** ✓ Passed**MOT #7** 2017-11-03 15:43**MOT test number** 667905574520**Result** ✓ Passed**Advice** All 4 tyre treads low**MOT #6** 2016-10-28 13:18**MOT test number** 370271641078**Result** ✓ Passed**Advice** Front tyres low**MOT #5** 2015-11-27 17:19**MOT test number** 839948929517**Result** ✓ Passed

**MOT #4** 2014-11-24 14:03**MOT test number** 678178624300**Result** ✓ Passed**MOT #3** 2013-11-29 09:54**MOT test number** 719593733311**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2012-11-30 15:59**MOT test number** 527035232395**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2012-11-30 15:59**MOT test number** 896175032375**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Centre Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
20 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 246 |
| MOT expiry date | 20 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2010-01-25 |
| Last registration | 2023-05-30 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-01-25 | 28 mi |
| Registration #2 | 2012-11-30 | 22.290 mi |
| Registration #3 | 2013-11-29 | 29.880 mi |
| Registration #4 | 2014-11-24 | 36.438 mi |
| Registration #5 | 2015-11-27 | 39.861 mi |
| Registration #6 | 2016-10-28 | 42.797 mi |
| Registration #7 | 2017-11-03 | 45.339 mi |
| Registration #8 | 2018-11-02 | 47.084 mi |
| Registration #9 | 2019-05-29 | 50.277 mi |
| Registration #10 | 2020-05-29 | 55.277 mi |
| Registration #11 | 2021-05-29 | 59.277 mi |
| Registration #12 | 2022-05-29 | 63.277 mi |
| Registration #13 | 2023-05-30 | 67.277 mi |
| Registration #14 | 2024-05-30 | 71.277 mi |
| Registration #15 | 2025-05-30 | 75.277 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1991 mm |
| Height | 1497 mm |
| Length | 4342 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1347 kg |
| Max. allowed weight | 1835 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | AL29261 |