



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Grey
Year of manufacture	2014
Top speed	113 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-24
Pictures	6
Listing price	View report

6.9 APR


Now offering finance rates from as low as 6.9% APR

6.9 APR

AutoTrader

Highly Rated

FOR OUR CUSTOMER SERVICE 2020



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-31
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	29
Total items failed	0

MOT #10	2024-03-25 16:57
MOT test number	573313051815
Result	✓ Passed
Next expiry date	2025-03-31
Advice	Rear Child Seat fitted not allowing full inspection of adult belt both sides
Minor	Nearside Front Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

**MOT #9**

2024-03-25 10:01

MOT test number

640224500683

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt both sides**Minor** Nearside Front Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing BOTH SIDES (5.2.3 (d) (ii))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Rear Tyre has a cut but not deep enough to reach the ply or cords BOTH SIDES (5.2.3 (d) (i))**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Nail in tyre**Advice** Rear Inner Tyre worn close to legal limit/worn on edge BOTH SIDES (5.2.3 (e))**MAJOR** Nearside Front Body component damaged and likely to cause injury side repeater lens slightly broken (6.2.1 (a) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**MOT #8** 2023-03-17 10:49**MOT test number** 719095056419**Result** ✓ Passed**Advice** TPMS light on dash**Advice** Rear Rear brake pads unable to be inspected, advised to have wheel removed and assessed.**Advice** Rear Tyre slightly damaged/cracking or perishing 225/55R18 Both rear tyres (5.2.3 (d) (ii))**Minor** Nearside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Nearside Front Lower Fog light not working**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2022-03-28 09:30**MOT test number** 574133973686**Result** ✓ Passed**MOT #6** 2022-03-28 08:01**MOT test number** 552830493821**Result** ✗ Failed**DANGEROUS** Brake pad(s) less than 1.5 mm thick both front (1.1.13 (a) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**MOT #5** 2021-04-01 12:30**MOT test number** 143697910040**Result** ✓ Passed

**MOT #4** 2020-03-19 14:29**MOT test number** 614831250587**Result** ✓ Passed**Advice** Nearside Front Nail in tyre**Advice** T.P.M.S Light on**Advice** All tyres wearing on edges**MOT #3** 2019-03-07 13:18**MOT test number** 779668877474**Result** ✓ Passed**Advice** Under trays fitted**Advice** Engine covers fitted**MOT #2** 2018-03-08 14:17**MOT test number** 836738066539**Result** ✓ Passed**MOT #1** 2017-03-08 15:20**MOT test number** 517160522243**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 March 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	31 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-31
Last registration	2024-03-25
Complete history	See info



Registration #1	2014-03-31	9 mi
Registration #2	2017-03-08	13.016 mi
Registration #3	2018-03-08	18.961 mi
Registration #4	2019-03-07	25.287 mi
Registration #5	2020-03-19	29.886 mi
Registration #6	2021-04-01	31.197 mi
Registration #7	2022-03-25	31.277 mi
Registration #8	2023-03-25	31.277 mi
Registration #9	2024-03-25	31.277 mi
Registration #10	2025-03-25	31.277 mi
Registration #11	2026-03-25	31.277 mi
Registration #12	2027-03-25	31.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1712 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HAEZ046175