



AVI4YPO

report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA S AC
Colour	Blue
Year of manufacture	2014
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	C








Internet history

Entry 1

Date	2022-01-29
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-06
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #10	2024-01-31 11:00
MOT test number	688866292108
Result	✓ Passed
Next expiry date	2025-02-06
Minor	Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #9	2023-02-03 13:53
MOT test number	941059130550
Result	✓ Passed
Minor	Central Lower Windscreen damaged but not adversely affecting driver's view Chipped (3.2 (a) (i))

MOT #8	2022-02-07 09:50
MOT test number	584700182216
Result	✓ Passed
Minor	Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #7** 2022-02-05 11:58**MOT test number** 591905886483**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #6** 2021-06-29 10:39**MOT test number** 770727529462**Result** ✓ Passed**Minor** Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #5** 2021-06-26 08:20**MOT test number** 953196009703**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #4** 2020-06-30 08:03**MOT test number** 160629301121**Result** ✓ Passed**Advice** O/S/F & Both rear tyres severely perished/splitting in tread area**Advice** Rear number plate dirty**Minor** Windscreen damaged but not adversely affecting driver's view Large chip swept area (3.2 (a) (i))



MOT #3	2019-06-11 09:22
MOT test number	497420314943
Result	✓ Passed
MOT #2	2018-06-19 12:31
MOT test number	766507258145
Result	✓ Passed
MOT #1	2017-06-29 09:04
MOT test number	300618992563
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
26 April 2024

✓

MOT

Expires:
6 February 2025

Tax status	Expired at 26 April 2024
Days left	4 days too late
MOT expiry date	6 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 AV14YPO
Plate since	2019-03-29
Current registration	 AV14YPO
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-07-11
Last registration	2024-01-31
Complete history	See info



Registration #1	2014-07-11	24 mi
Registration #2	2017-06-29	37.661 mi
Registration #3	2018-06-19	49.707 mi
Registration #4	2019-06-11	60.315 mi
Registration #5	2020-06-30	71.272 mi
Registration #6	2021-06-26	81.790 mi
Registration #7	2022-06-26	91.277 mi
Registration #8	2023-06-26	101.277 mi
Registration #9	2024-01-31	111.277 mi
Registration #10	2024-01-31	121.277 mi
Registration #11	2024-01-31	131.277 mi
Registration #12	2024-01-31	141.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1000 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	K12B - 1808086LUY