





report date: 2024-03-29

# General information

Make	MERCEDES
Model	B-CLASS B200 SE
Colour	Black
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	1 speed CVT

# Engine & fuel consumption

Power	134 BHP
Max. torque	185 Nm at 4.000 rpm
Engine capacity	2.035 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	175 g/km
CO2 label	Н



CarCheck.co.uk page 1/13




# Internet history

# Entry 1

Date 2021-08-07

Pictures 22

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

2021-02-13 15:37

MOT	history
1.101	iliocol y

MOT #16

MOT expiry date	2023-05-09
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	22
Total items failed	5

MOT #17	2022-05-10 10:23
MOT test number	231907613161
Result	<b>√</b> Passed
Next expiry date	2023-05-09
Advice Under trays	

MOT test number	541892660243
Result	<b>✓</b> Passed
MOT #15	2020-02-25 17:00
MOT test number	830261785990

MOT #14	2019-02-25 12:56
MOT test number	934517075661
Result	✓ Passed

MOT #13	2019-02-25 12:56
MOT test number	317190360969
Result	<b>X</b> Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 3/13



**MOT #12** 

**GU07UYL** 

report date: 2024-03-29

2018-02-10 09:08

MOT test number 168492909488

**Result** ✓ Passed

**MOT #11** 2018-02-09 11:30

**MOT test number** 193988409537

Result X Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

Fail Windscreen washer provides insufficient washer liquid jets blocked, (8.2.3)

**Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced bulb incorrectly fitted, (1.7.5a)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #10** 2017-02-06 17:29

MOT test number 929438760813

Result \( \sqrt{Passed} \)

**MOT #9** 2016-01-29 15:40

**MOT test number** 364897064805

Result \( \sqrt{Passed} \)

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

Advice

Oil leaks

CarCheck.co.uk page 4/13



MOT #8 2016-01-29 15:40

MOT test number 580336779600

Result X Failed

**Pass with rectification** Rear Direction indicators incorrect colour (1.4.A.2f)

Advice Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**Advice** Oil leaks

MOT #7 2015-01-19 12:10

**MOT test number** 736699115081

**Result** ✓ Passed

**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)

MOT #6 2014-02-06 15:15

**MOT test number** 985737734070

**Result** 
✓ Passed

**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5 2013-02-15 16:48

MOT test number 176546143096

**Result** ✓ Passed

Advice Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 5/13



MOT #4 2012-02-13 13:46

**MOT test number** 657754142029

**Notice** Rear tyres unevenly worn

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Rear brake pads wearing low

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2012-01-10 08:51

**MOT test number** 226730112048

Result 

Passed

MOT #2 2011-01-28 10:30

**MOT test number** 735608121049

**Result** ✓ Passed

**MOT #1** 2010-01-18 10:37

**MOT test number** 902488510087

**Result** 
✓ Passed

Notice Undertray fitted to floor

CarCheck.co.uk page 6/13



Tax & MOT check

Tax expired: 1 May 2023



**Expired:** 9 May 2023 X MOT

\_\_\_\_

Tax status Expired at 1 May 2023

Days left 365 days too late

MOT expiry date 9 May 2023

Full MOT history See MOT history

### Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29


### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <a href="here">here</a> for the results.

### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



### Extra MERCEDES salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

### Owner history

Owner mistory	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	
***************************************	
***************************************	
2000000	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK SIF
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-01
Last registration	2022-05-10
Complete history	See info



Registration #1	2007-03-01	14 mi
Registration #2	2010-01-18	13.155 mi
Registration #3	2011-01-28	15.056 mi
Registration #4	2012-01-10	21.944 mi
Registration #5	2012-02-13	21.954 mi
Registration #6	2013-02-15	32.243 mi
Registration #7	2014-02-06	46.939 mi
Registration #8	2015-01-19	58.963 mi
Registration #9	2016-01-29	63.735 mi
Registration #10	2016-01-29	63.735 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		70.777 au

More info >

CarCheck.co.uk page 12/13



# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1345 kg

# Additional information

Fuel tank capacity	54
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26696030341979

CarCheck.co.uk page 13/13