



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D4 R-DESIGN LUX NAV
Colour	Grey
Year of manufacture	2016
Top speed	143 mph
0 - 60 mph	7.1 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C




**Internet history****Entry 4**

Date	2023-02-26
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)**Entry 3**

Date	2021-12-25
Pictures	26
Listing price	View report

source: [yesauto.com](#)**Entry 2**

Date	2021-12-16
Pictures	26
Listing price	View report

source: [cargurus.co.uk](#)**Entry 1**

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-27
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #6	2024-02-26 13:33
MOT test number	370913806971
Result	✓ Passed
Next expiry date	2025-02-27

MOT #5	2023-02-28 17:21
MOT test number	937581475984
Result	✓ Passed

- AdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))
- AdviceOffside Front wiper slightly smearing
- AdviceFront Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4** 2021-12-14 10:39**MOT test number** 686309696234**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2021-05-14 10:03**MOT test number** 622640670263**Result** ✓ Passed**MOT #2** 2020-07-06 11:17**MOT test number** 911352168028**Result** ✓ Passed**MOT #1** 2019-04-23 11:38**MOT test number** 395407435509**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
27 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YP16PVX
Plate since	2019-09-28
Current registration	YP16PVX
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-05-02
Last registration	2024-02-26
Complete history	See info



Registration #1	2016-05-02	26 mi
Registration #2	2019-04-23	82.262 mi
Registration #3	2020-07-06	109.138 mi
Registration #4	2020-05-20	109.277 mi
Registration #5	2021-05-14	114.744 mi
Registration #6	2021-12-14	117.000 mi
Registration #7	2022-05-20	121.277 mi
Registration #8	2022-05-20	121.277 mi
Registration #9	2022-05-20	121.277 mi
Registration #10	2022-05-20	121.277 mi
Registration #11	2024-02-26	121.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1547 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1582767