





report date: 2024-03-29

General information

Make	KIA
Model	CEED CRDI GT-LINE ISG
Colour	Silver
Year of manufacture	2018
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	280 Nm at 3.000 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	В



CarCheck.co.uk page 1/12




Internet history

Entry 4

Date 2022-01-20

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 3

Date	2021-12-26	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

Entry 2

Date 2021-12-09


Pictures 32

Listing price <u>View report</u>









source: yesauto.com

Entry 1

CarCheck.co.uk page 2/12

Pictures 12


Listing price

View report









source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-04
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	14
Total items failed	5

MOT #5		2024-04-05 16:02
MOT test	number	918316642677
Result		✓ Passed
Next expi	ry date	2025-04-04
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))		
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



MOT #4 2024-04-05 12:01

MOT test number 490951353337

Result X Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge on 1.6 mm & worn inner edge (5.2.3 (e))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 225/45/r17 (5.2.3 (d) (i))

Fail Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))

MOT #3 2023-02-21 09:09

MOT test number 136299873912

Result

Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #2 2022-02-24 13:11

MOT test number 843630061555

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #1 2021-02-05 10:57

MOT test number 100782623531

CarCheck.co.uk page 5/12



Tax & MOT check





Tax expired: 16 April 2024

Tax status	Expired at 16 April 2024
Days left	14 days too late
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Expires: 4 April 2025

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	OK OK
Plate since	
Current registration	OK STE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-03-02
Last registration	2024-04-05
Complete history	See info



Registration #1	2018-03-02	10 mi
Registration #2	2021-02-05	34.189 mi
Registration #3		9.377 es
Registration #4		71.777 66
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditionin
S0295	
50482	
60501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1493 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	53 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number D4FBHZ185546