



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE TSI
Colour	White
Year of manufacture	2015
Top speed	114 mph
0 - 100 km/h	10.8 seconds
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	160 Nm at 1.400 rpm
Engine capacity	1.197 cc
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	107 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-09-24
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-10-17
<b>MOT pass rate</b>	75 %
<b>MOT passed</b>	6
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	14
<b>Total items failed</b>	4

**MOT #8** 2023-10-07 09:04**MOT test number** 308090419990**Result** Passed**Next expiry date** 2024-10-17**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside park brake lower effort**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2022-10-18 11:53**MOT test number** 399638636450**Result** Passed**Advice** Rear handbrake arms on both rear calipers sticking making wheels to slightly bind**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2022-10-18 11:53**MOT test number** 555851416639**Result** ✗ Failed**Advice** Rear handbrake arms on both rear calipers sticking making wheels to slightly bind**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2021-10-14 10:20**MOT test number** 353065593221**Result** ✓ Passed**MOT #4** 2020-09-28 08:14**MOT test number** 967575805512**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #3** 2019-09-30 08:00**MOT test number** 916411817703**Result** ✓ Passed



MOT #2	2019-09-27 10:38
MOT test number	580542917717
Result	✗ Failed
Fail	Offside Parking brake inoperative on one side (1.4.1 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Service brake excessively binding (1.2.1 (f))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2018-09-21 10:56
MOT test number	189202137634
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
17 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	17 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-30
Last registration	2023-10-07
Complete history	<a href="#">See info</a>



Registration #1	2015-09-30	10 mi
Registration #2	2018-09-21	22.476 mi
Registration #3	2019-09-27	27.275 mi
Registration #4	2019-09-30	27.311 mi
Registration #5	2020-09-28	30.860 mi
Registration #6	2020-09-28	30.860 mi
Registration #7	2020-09-28	30.860 mi
Registration #8	2020-09-28	30.860 mi
Registration #9	2020-09-28	30.860 mi
Registration #10	2020-09-28	30.860 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1901 mm
Height	1462 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1007 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	CJZC437240